

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPL
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. NM-10191	
2. NAME OF OPERATOR Hondo Oil & Gas Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P. O. Box 2208, Roswell, NM 88202		7. UNIT AGREEMENT NAME East Shugart Unit	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 2380' FSL & 1680' FWL		8. FARM OR LEASE NAME East Shugart	
14. PERMIT NO.		9. WELL NO. 33	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3619' GR		10. FIELD AND POOL, OR WILDCAT Shugart Yates, 7R-Qn-Grbg	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 34-T18S-R31E	
		12. COUNTY OR PARISH Eddy Co.,	
		13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☒
SHOOTING OR ACIDIZING ☒
(Other) ☐

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Perforated 2606', 08', 10', 12', 14', 90', 91', 92', 93', 94', 95', 96', 97', 98', 2699', 2700', 01', 02', 03', 04', 05', 06', 07', 08', 2716', 17', 18', 49', 50', 51', 52', 72', 73', 74', 75', 76', 2777' (74 holes).

Acidized 2690'-2777' w/ 4000 gals 15% NeFe, ISIP 1232 psi.

Acidized 2606'-2614' w/ 2000 gals 15% NeFe, ISIP 930 psi.

Frac'd 2606'-2777' w/ 30,000 gals 40# Bora gel carrying 60,000# 12-20 sand, ISIP 1418 psi.

Frac'd 2690'-2777' w/ 21,000 gals 30# crosslinked gel & 31,000# 12-20 sand, ISIP 1390 psi.

Put to pump & test. Temporarily abandon for further evaluation.

POH w/ tbg & rods put valve on wellhead.

18. I hereby certify that the foregoing is true and correct

SIGNED E. L. Buttross, Jr.
E. L. Buttross, Jr.

TITLE Petroleum Engineer

DATE 04/02/91

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

*See Instructions on Reverse Side

ACCEPTED FOR RECORD

DATE

SJS

CARLSBAD, NEW MEXICO