Submit 3 Copies	-	tate of New Mer	kico sources Department	Form C-103 Revised 1-1-89
o Appropriale District Office				
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONS	ERVATIO	N DIVISION	WELL API NO.
DISTRICT II		New Mexico	8 RT RECEIVED	30-015-26498
P.O. Drawer DD, Artesia, NM 882	210		07504 2000	5. Indicate Type of Lease STATE FEE X
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM	87410		JAN 10 '91	6. State Oil & Gas Lease No.
(DO NOT USE THIS FORM FORM FORM	NOTICES AND REPO OR PROPOSALS TO DRILL RESERVOIR. USE "APPLI ORM C-101) FOR SUCH PR	OR TO DEEPEN	OR PĽÚG BAČÍC TO A	7. Lease Name or Unit Agreement Name
. Type of Well: OL GA WELL WE	s. X	OTHER		Winston AII
Name of Operator				8. Well No.
YATES PETROLEUM	CORPORATION ✓	(505) 74	8-1471	
Address of Operator 105 South 4th St	., Artesia, New M	Mexico 882	10	9. Pool name or Wildcat Undes. Boyd Morrow Gas
. Well Location				West
Unit Letter \underline{E} :	1980 Feet From The _	North	Line and660	Feet From The West Line
Section 14	IOWEEDID	9S Rai	24E	NMPM Eddy County
	10. Elevat	ion (Show whether 1 3657' GR	DF, RKB, RT, GR, etc.)	<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>
	heck Appropriate Bo			Report, or Other Data
	nore uppropriate po			
NOTICE C	FINTENTION TO:		SUE	BSEQUENT REPORT OF:
ERFORM REMEDIAL WORK			REMEDIAL WORK	
NOTICE C ERFORM REMEDIAL WORK EMPORARILY ABANDON			REMEDIAL WORK	G OPNS.
ERFORM REMEDIAL WORK EMPORARILY ABANDON ULL OR ALTER CASING	PLUG AND AR CHANGE PLA		REMEDIAL WORK	G OPNS.
ERFORM REMEDIAL WORK EMPORARILY ABANDON ULL OR ALTER CASING THER: Request_permis	PLUG AND AR CHANGE PLA		REMEDIAL WORK	G OPNS.
ERFORM REMEDIAL WORK EMPORARILY ABANDON ULL OR ALTER CASING OTHER: Request permis pending N	PLUG AND	well X	REMEDIAL WORK COMMENCE DRILLIN CASING TEST AND C OTHER:	G OPNS.
ERFORM REMEDIAL WORK EMPORARILY ABANDON ULL OR ALTER CASING THER: Request permis pending NS 12 Describe Proposed or Complet work) SEE RULE 1103. 1-9-91. Well is for January 24, Verbal permissio well to pipeline	PLUG AND	well X periment details, and tion for Mon 1991 for M ke Williams yell cleaned	REMEDIAL WORK COMMENCE DRILLIN CASING TEST AND C OTHER: d give pertinent dates, inclu- crow completion NSL approval. s, Supervisor, d up and not let	ALTERING CASING G OPNS. PLUG AND ABANDONMENT EMENT JOB wding estimated date of starting any proposed A hearing has been set Well was frac'd 1-8-91. NMOCD, Artesia, NM to connect eave frac water in well.
ERFORM REMEDIAL WORK EMPORARILY ABANDON ULL OR ALTER CASING THER: Request permis pending NS 12 Describe Proposed or Complet work) SEE RULE 1103. 1-9-91. Well is for January 24, Verbal permissio well to pipeline If NSL is not ap	PLUG AND AND CHANGE PLA CHANGE PL	well X perimens details, and ion for Mon 1991 for M ke Williams yell cleaned on January	REMEDIAL WORK COMMENCE DRILLIN CASING TEST AND C OTHER: d give pertinent dates, inclu- crow completion NSL approval. s, Supervisor, d up and not let	ALTERING CASING G OPNS. PLUG AND ABANDONMENT EMENT JOB wding estimated date of starting any proposed A hearing has been set Well was frac'd 1-8-91. NMOCD, Artesia, NM to connect eave frac water in well.
ERFORM REMEDIAL WORK EMPORARILY ABANDON ULL OR ALTER CASING THER: Request permis pending NS 12 Describe Proposed or Complet work) SEE RULE 1103. 1-9-91. Well is for January 24, Verbal permissio well to pipeline If NSL is not ap	PLUG AND AND CHANGE PLA CHANGE PLA CHANGE PLA Change PLA Si oproval. ed Operations (Clearly state all unorthodox locat 1991 in Santa Fe, n obtained from Mi 1-10-91 to get w proved at hearing	well X perimens details, and ion for Mon 1991 for M ke Williams yell cleaned on January	REMEDIAL WORK COMMENCE DRILLIN CASING TEST AND C OTHER: d give pertinent dates, inclu- crow completion NSL approval. s, Supervisor, d up and not let	ALTERING CASING G OPNS. PLUG AND ABANDONMENT EMENT JOB wding estimated date of starting any proposed A hearing has been set Well was frac'd 1-8-91. NMOCD, Artesia, NM to connect eave frac water in well.
ERFORM REMEDIAL WORK EMPORARILY ABANDON ULL OR ALTER CASING THER: Request permis pending NS 12 Describe Proposed or Complet work) SEE RULE 1103. 1-9-91. Well is for January 24, Verbal permissio well to pipeline If NSL is not ap	PLUG AND AND CHANGE PLA CHANGE PLA CHANGE PLA Change PLA Si oproval. ed Operations (Clearly state all unorthodox locat 1991 in Santa Fe, n obtained from Mi 1-10-91 to get w proved at hearing	well X perimens details, and ion for Mon 1991 for M ke Williams yell cleaned on January	REMEDIAL WORK COMMENCE DRILLIN CASING TEST AND C OTHER: d give pertinent dates, inclu- crow completion NSL approval. s, Supervisor, d up and not let	ALTERING CASING G OPNS. PLUG AND ABANDONMENT EMENT JOB wding estimated date of starting any proposed A hearing has been set Well was frac'd 1-8-91. NMOCD, Artesia, NM to connect eave frac water in well.
ERFORM REMEDIAL WORK EMPORARILY ABANDON ULL OR ALTER CASING THER: Request permis pending NS 12 Describe Proposed or Complet work) SEE RULE 1103. 1-9-91. Well is for January 24, Verbal permissio well to pipeline If NSL is not ap	PLUG AND AND CHANGE PLA CHANGE PLA CHANGE PLA Change Pla Constant of the produce of Constant of the produce of Change Pla Change Pla	well X periment details, and ion for Mon 1991 for Mon 1991 for Mon ke Williams yell cleaned on January orrow.	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND C OTHER: d give pertinent dates, inclu- trow completion NSL approval. s, Supervisor, d up and not le y 24th, will sh	ALTERING CASING G OPNS. PLUG AND ABANDONMENT EMENT JOB wding estimated date of starting any proposed A hearing has been set Well was frac'd 1-8-91. NMOCD, Artesia, NM to connect eave frac water in well. Nut well in.
ERFORM REMEDIAL WORK EMPORARILY ABANDON ULL OR ALTER CASING OTHER: Request permiss pending NS 12 Describe Proposed or Complet work) SEE RULE 1103. 1-9-91. Well is for January 24, Verbal permissio well to pipeline If NSL is not ap Perforations ope	PLUG AND	well X periment details, and ion for Mon 1991 for Mon 1991 for Mon ke Williams yell cleaned on January orrow.	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND C OTHER: d give pertiment dates, inclu- rrow completion NSL approval. s, Supervisor, d up and not le y 24th, will sh	ALTERING CASING G OPNS. PLUG AND ABANDONMENT EMENT JOB uding estimated date of starting any proposed A. A hearing has been set Well was frac'd 1-8-91. NMOCD, Artesia, NM to connect eave frac water in well. nut well in. UDENTIFY DATE 1-9-91
ERFORM REMEDIAL WORK EMPORARILY ABANDON ULL OR ALTER CASING OTHER: Request permis pending NS 12 Describe Proposed or Complet work) SEE RULE 1103. 1-9-91. Well is for January 24, Verbal permissio well to pipeline If NSL is not ap Perforations ope	PLUG AND AND CHANGE PLA CHANGE PLA CHANGE PLA Change Pla Constant of the produce of Constant of the produce of Change Pla Change Pla	well X periment details, and ion for Mon 1991 for Mon 1991 for Mon ke Williams yell cleaned on January orrow.	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND C OTHER: d give pertinent dates, inclu- trow completion NSL approval. s, Supervisor, d up and not le y 24th, will sh	ALTERING CASING G OPNS. PLUG AND ABANDONMENT EMENT JOB wding estimated date of starting any proposed A hearing has been set Well was frac'd 1-8-91. NMOCD, Artesia, NM to connect eave frac water in well. Nut well in.
ERFORM REMEDIAL WORK EMPORARILY ABANDON ULL OR ALTER CASING OTHER: Request permiss pending NS 12 Describe Proposed or Complete work) SEE RULE 1103. 1-9-91. Well is for January 24, Verbal permissio well to pipeline If NSL is not ap Perforations ope	PLUG AND	well X perimens details, and ion for Mon 1991 for Mon 1991 for Mon ke Williams yell cleaned on January orrow.	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND C OTHER: d give pertinent dates, inclu- trow completion NSL approval. s, Supervisor, d up and not le y 24th, will sh	ALTERING CASING G OPNS. PLUG AND ABANDONMENT EMENT JOB uding estimated date of starting any proposed A. A hearing has been set Well was frac'd 1-8-91. NMOCD, Artesia, NM to connect eave frac water in well. nut well in. UDENTIFY DATE 1-9-91

Submit to Appropriate District Office State Lease - 4 copies Fee Lease - 3 copies

Ł

DISTRICT J P.O. Box 1980, Hobbs, NM 88240

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410

State of New Mexico Energy, Minerals and Natural Resources Dep., nent

RECENTED

Form C-102 Revised 1-1-89

OIL CONSERVATION DIVISION P.O. Box 2088

Santa Fe, New Mexico 87504-2088

O. C. U. ARTESIA, OFFICE

JAN 10 101

	•		AKI
WELL LOCATION AND	ACREAGE	DEDICATION PL	.AT

All Distances must be from the outer boundaries of the section

Operator			Lease			Well No.	
YATES PETROLEU	JM CORPORATION		Winston	AII		1	
Unit Letter Section	on Township		Range		County		
E 14	19 South		24 East	NMPM	E	ddy	
Actual Footage Location of							
	rom the North	line and	660 Pool	feet from t	<u>he East</u>	line Dedicated Acreage	
Ground level Elev.	Producing Formation			2		•	
3657'	Morrow reage dedicated to the subject well	by colored pen	Undes. Boyd Mo	rrow Gas		320	Acres
2. If more than of an unitization, fo yes If answer is "no' this form is "neod No attourable with	one lease is dedicated to the well, ou one lease of different ownership is d ree-pooling, etc.? No If answ 'list the owners and tract descriptio sessary.	utline each and ledicated to the wer is "yes" typ ans which have interests have be	identify the ownership there well, have the interest of all e of consolidation actually been consolidated. sen consolidated (by commu	of (both as to workin owners been consoli (Use reverse side of	dated by comm	nunitization,	
or until a non-st	andard unit, eliminating such interes	st, has been app	proved by the Division.	· · · · · · · · · · · · · · · · · · ·			
-0861 				6 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9	I hereby ontained herei est of my know ignature www.ignature wwwy.ignature wwww.ignature www.ignature www.ignature www.ign	ON SUPERVIS	information splete to the UST OR PORATIO
					on this plat o actual survey. supervison, au correct to th belief. Dute Surveyed	o original cal of dated urveyor	field notes of or under my is true and owledge and
0 330 660 990	1320 1650 1980 2310 20	640 2	000 1500 1000	500 0			