

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-015-26669

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	RECEIVED OCT 25 1991 O. C. D. ARTESIA OFFICE
2. Name of Operator YATES PETROLEUM CORPORATION	7. Lease Name or Unit Agreement Name Huisache AHI Com
3. Address of Operator 105 South 4th St., Artesia, NM 88210	8. Well No. 2
4. Well Location Unit Letter I : 1855 Feet From The South Line and 660 Feet From The East Line Section 2 Township 20S Range 24E NMPM Eddy County	9. Pool name or Wildcat North Dagger Draw U/Penn
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3616' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Perforate, Treat <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-15-91. Drilled out DV tool at 5603'. Perforated 7658-7786' w/44 - .50" holes as follows:
7658, 60, 62, 72, 74, 76 (12 holes-2 SPF); 7710, 12, 14, 16, 18, 32, 34, 36, 38 (18 holes-2 SPF); 7765, 67, 69, 70, 83, 84, 86 (14 holes-2 SPF)
Acidized perfs 7765-86' w/700 gals 20% NEFE acid. Communicated with upper perfs.
Acidized perfs 7710-86' w/700 gals 20% NEFE acid. Communicated with upper perfs.
Acidized perfs 7658-76' w/700 gals 20% NEFE acid.
Acidized perfs 7658-7786' w/15000 gals 20% NEFE acid and 24 ball sealers.
10-19-91. Running sub-pump.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 10-22-91
TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY
MIKE WILLIAMS

APPROVED BY SUPERVISOR, DISTRICT II

TITLE DATE NOV - 6 1991

CONDITIONS OF APPROVAL, IF ANY: