

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2083
Santa Fe, New Mexico 87504-2083

AUG 20 1991

O. C. D.

WELL API NO.
30-015-26746

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

John AGU

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
YATES PETROLEUM CORPORATION

8. Well No.
4

3. Address of Operator
105 South 4th St., Artesia, NM 88210

9. Pool name or Wildcat
South Dagger Draw U/Penn

4. Well Location
Unit Letter H : 1980 Feet From The North Line and 660 Feet From The East Line
Section 14 Township 20S Range 24E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3610' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Production Casing, Perforate, Treat ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 8280'. Reached TD 8-9-91. Ran 200 jts 7" 26# and 23# J-55 and N-80 casing set 8280'. Float shoe set 8280', float collar set 8244'. DV tool set 5407'. Cmt'd stage I - 1000 gals Super Flush 101, 650 sx Class "H" with 10#/sx Gilsonite, 5#/sx Salt, .4% Halad 22A, .3% CFR-3, (yield 1.35, wt 15.2). PD 1:15 AM 8-11-91. Circ 140 sx. Opened DV tool with 1000 psi. Circ 1-1/4 hrs. Stage II - 700 sx Halliburton Lite with 1/4#/sx Flocele, 5#/sx Gilsonite (yield 1.84, wt 12.6). Tailed in w/100 sx Class "H" Neat (yield 1.18, wt 15.6). PD 4:30 AM 8-11-91. Closed DV tool with 3200 psi, held OK. Bumped plug to 1900 psi for 2 mins, float and casing held okay. Circ 120 sx. WOC 24 hrs. Drilled DV tool at 5407'. Perforated 7640-7784' w/58 - .50" holes (2 SPF) as follows: 7640, 42, 44, 46, 48, 50, 7709, 12, 14, 16, 18, 20, 22, 24, 7756, 58, 60, 62, 64, 66, 68, 70, 72, 74, 76, 78, 80, 82 and 7784'. Acidized all perfs 7709-7784' w/6500g. 20% NEFE acid; perfs 7640-50' w/800g. 20% NEFE acid. Acidized all perfs 7640-7784' w/25000g. 20% NEFE acid, 800# rock salt, 400# acid flakes + 28 ball sealers.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett

TITLE Production Supervisor

DATE 8-19-91

TYPE OR PRINT NAME

Juanita Goodlett

TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR, DISTRICT II

TITLE

DATE

AUG 21 1991

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY: