

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTRECEIVED
OCD - HITESIA
SUNDY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an
abandoned well. Use Form 3160-3 (APD) for such proposals.FORM APPROVED
OMB No. 1004-0135
Expires November 30, 2000

5. Lease Serial No.
NM 86554

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.
ARRINGTON FED #1

9. API Well No.
30015267560051

10. Field and Pool, or Exploratory Area
SHUGART Y, SR, Q

11. County or Parish, State
EDDY County, NM

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well
☐ Oil Well ☐ Gas Well ☒ Other

2. Name of Operator
SNACKELFORD OIL CO. I

3a. Address
P.O. BOX 10665 MIDLAND, TX

3b. Phone No. (include area code)
915-682-9784

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
330' FNL + 2310' FNL SEC. 14 T19S R31E

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input checked="" type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Feb. 11, 2002

TH Approved For 12 Month Period

Ending 2/11/2003

- 1) POOH w/ tubing
- 2) GIH w/ CIBP AND set 50 ft. above perf. - where?
- 3) Dump 35 ft. cement plug on top of CIBP Footage
- 4) LOAD HOLE AND pressure tested to 500 psi for 30 minutes. Held OK.

This well is being TRIED to have an alternative disposal.
well should our disposal system have problems.

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

DON SNACKELFORD

Title Owner

Signature

Date February 12, 2002

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approv
Condi
certify
which

Accepted for record

does not warrant or
in the subject lease

Title

Date

3/4/2002

Office

CFC

Title
States

only MAR 6 2002

I a crime for any person knowingly and willfully to make to any department or agency of the United
to any matter within its jurisdiction.

