

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

NOV 11 1991

O. C. D.

ARTESIA OFFICE

WELL API NO.

30-015-26826

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Parish IV Com

8. Well No.

5

9. Pool name or Wildcat

North Dagger Draw U/Penn

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

YATES PETROLEUM CORPORATION ✓

3. Address of Operator

105 South 4th St., Artesia, NM 88210

4. Well Location

Unit Letter P : 915 Feet From The South Line and 660 Feet From The East Line

Section

19

Township

19S

Range

25E

NMPM

Eddy

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3547' GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Set 7" casing ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 8250'. Reached TD 11-5-91. Ran 197 jts 7" 23# and 26# J-55 and N-80 casing set at 8248'. Float shoe set 8248', float collar set 8207'. DV tool set 5323'. Cmt'd in 2 stages: Stage 1: 500 gals Surebond + 825 sx Class "H" with 5#/sx CSE + .65% CF-14 + 5#/sx Gilsonite + 1/4#/sx Celloseal (yield 1.31, wt 15.1). PD 3:15 PM 11-6-91. Circulate thru DV tool 2 hrs. Circulate 150 sacks. Stage 2: 1000 sx Pacesetter Lite "C" with 5#/sx salt + 4/10% CF-14 + 5#/sx Gilsonite + 1/4#/sx Celloseal (yield 1.98, wt 12.4). Tailed in w/100 sx Class "H" Neat (yield 1.18, wt 15.6). PD 7:00 PM 11-6-91. Circulated 175 sacks. Close DV tool with 3000#. Bumped plug to 2000 psi, float and casing held OK. WOC 18 hrs.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE

Production Supervisor

DATE

11-7-91

TYPE OR PRINT NAME

Juanita Goodlett

TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY

MIKE WILLIAMS

SUPERVISOR, DISTRICT II

TITLE

DATE

NOV 14 1991

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY: