Form 3160-5 (June 1990)

TED STATES DEPARTMENT OF THE INTERIOR

OIL	VATION DIV FORM APPROVED Budget Bureau No. 1004-0135 AS OBSISE Designation and Serial No.	
911 S. 1st ST	0021612634March 31, 1993	
ARTESIA, N	115. Dease Designation and Serial No.	
ANILO	NM-13409	
	6. If Indian, Allonee or Tribe Name	
lifferent reservoir.	•	
s		
	7. If Unit or CA. Agreement Designation	
	7. If the of CA, Aprenies besignation	
	8. Well Name and No.	
	Lakeshore Federal #1	
	9. API Well No.	
	30-015-26835	
5005	10. Field and Pool; or Exploratory Area	
5905	Fact Lake Norrow	
	11. County or Parish, State	
	Eddy County, N.M.	
NOTICE, REPORT, OR OTHER DATA		

BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a d Use "APPLICATION FOR PERMIT-" for such proposal SUBMIT IN TRIPLICATE 1. Type of Well Oil Well 2. Name of Operator Mewbourne Oil Company 3. Address and Telephone No. P.O. Box 5270 Hobbs, New Mexico 88241

4. Location of Well (Footage: Sec., T., R., M., or Survey Description) (505) 393-990' FNL & 990' FEL Sec. 20-T19S-R27E CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF 12 TYPE OF ACTION TYPE OF SUBMISSION Change of Plans Abandonment Notice of laura **New Construction** Recompletion Non-Routine Fracturing Plugging Back Subsequent Report Water Shut-Off Casing Repair Conversion to Injection Altering Casing Final Abandonment Notice __ Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

MIRU pulling unit. Set CIBP @7825'. Cap plug w/35' cement. Load & circulate hole w/9.0 ppg mud. Cut & attempt to put 15-1/2" casing @3000'. \$35 Spot 150' cement plug across 5 1/2" stub & tag. Spot 100' cement plug across 8 5/8" casing shoe @2200' & tag. Spot 100' cement plug across 13 3/8" casing shoe @315'. Spot 50' surface plug. Set dry hole marker, cut

anchors and clean location. Will notify BLM 24 hours before starting.

ON THE PROPERTY OF

		Dier of
14. I hereby certify that the foregoing is true and correct Signed 1000000.	Tide Engineer	Detr Nov. 27, 1995
(This space for Federal or State office use) Approved by Ong Signed by Shannon J. Shaw Conditions of approval, if any	Tide PETROLEUM ENGINEER	Date 12/11/95

Elected Sign Section 1911 miles the common registers for empty and withhild in made to any inputment of the United States any including or fraudulent statements in representations to an increase earlier to