## Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, Minerals and Natural Resources Department

Form	C	-1Q	3
Revis	ed	1-1	-89

DISTRICT I		
P.O. Box 1980.	Hobbs, NM	88240

OIL CONSERVATION DIVISION P.O. Box 2088

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

PERFORM REMEDIAL WORK

TEMPORARILY ABANDON

**PULL OR ALTER CASING** 

OTHER:

Santa Fe, New Mexicon 275042088

WELL AFI NO.		
30-015-26	920	
5. Indicate Type of I	.ease	
	STATE	FEE X

**ALTERING CASING** 

PLUG AND ABANDONMENT

WELL ARENO

DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	MAR 1 1 1992	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON	WELLES OFFICE	
( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DE DIFFERENT RESERVOIR. USE "APPLICATION FO (FORM C-101) FOR SUCH PROPOSALS	7. Lease Name or Unit Agreement Name	
1. Type of Well: ORL GAS WELL X WELL OTHER		Sara AHA Com
2. Name of Operator YATES PETROLEUM CORPORATION		8. Well No. 6
3. Address of Operator 105 South 4th St., Artesia, NM 88210		9. Pool name or Wildcat South Dagger Draw U/Penn
4. Well Location		
Unit Letter P: 660 Feet From The South	Line and 660	Feet From The East Line
Section 11 Township 20S	Range 24E	NMPM Eddy County
10. Elevation (Show w	whether DF, RKB, RT, GR, etc.) 3612  GR	
11. Check Appropriate Box to Indi	cate Nature of Notice,	Report, or Other Data
NOTICE OF INTENTION TO:		BSEQUENT REPORT OF:

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-21-92. Drilled out DV tool @ 5586'. Perforated 7620-7764' w/42 - .50" holes as follows: 7620, 22, 24, 34, 36, 38, 60, 62, 64 and 7666' (2 SPF-20 holes); 7740, 42, 44, 46, 48, 50, 56, 58, 60, 62 and 7764' (2 SPF-22 holes). Acidized perfs 7620-7764' in three stages w/ 20000 gals 20% HCL NEFE acid. Put well on pump 2-24-92. Pumped well three days.

2-28-92. RUPU. Acidized perfs 7740-7764' w/20000g. 20% HCL NEFE. Acidized perfs 7620-7666'

REMEDIAL WORK

COMMENCE DRILLING OPNS.

CASING TEST AND CEMENT JOB

OTHER: Perforate, Treat

w/20000g. 20% HCL NEFE acid. Put well on pump 2-29-92.

PLUG AND ABANDON

**CHANGE PLANS** 

I hereby certify that the information above is true and complete to the best of m	y knowledge and belief.	
SIGNATURE Landa Davilless	Production Supervisor	DATE
TYPE OF FRINT NAME Juanita Goodlett		TELEPHONE NO. 505/748-1471

MIKE WILLIAMS

SUPERVISOR, DISTRICT ! #

MAR 2 6 1992

CONDITIONS OF APPROVAL JF ANY: