

CISF
Op

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

JUN 24 1992

O. C. D.

WELL API NO. 30-015-26977
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Roy AET
8. Well No. 4
9. Pool name or Wildcat North Dagger Draw U/Penn
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3545' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South 4th St., Artesia, NM 88210

4. Well Location Unit Letter 0 : 660 Feet From The South Line and 1980 Feet From The East Line Section 8 Township 19S Range 25E NMPM Eddy County
--

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3545' GR
--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Perforate, Treat <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
Perforated 7752-7814' w/26 - .50" holes (2 SPF) as follows: 7752, 54, 56 (6 holes), 7782, 84, 86 (6 holes), 7802, 04, 06, 08, 10, 12 and 7814' (14 holes). Straddle perfs 7802-14. Communicated thru perfs 7782-86'. Straddle 7782-7814'. Break at 3800 psi. Acidized w/900g. 20% NEFE acid. Communicated up. Closed annulus. Straddle all perfs. Acidized 7752-7814' w/10500 gals 20% NEFE acid with scale and paraffin inhibitor.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 6-19-92
TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)
APPROVED BY ORIGINAL SIGNED BY TITLE PRODUCTION SUPERVISOR DATE JUL 24 1992
CONDITIONS OF APPROVAL, IF ANY: