

Submit 3 Copies To Appropriate District
 Office
 District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 811 South First, Artesia, NM 88210
 District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM
 87505

State of New Mexico
 Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

-157

Form C-103
 Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
 Oil Well Gas Well Other

2. Name of Operator
Yates Petroleum Corporation

3. Address of Operator
105 S. 4th Street Artesia, NM 88210

4. Well Location
 Unit Letter I : 1830 feet from the South line and 890 feet from the East line
 Section 36 Township 19S Range 24E NMPM Eddy County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
3589' GR

WELL API NO.
30-015-26980

5. Indicate Type of Lease
 STATE FEE

6. State Oil & Gas Lease No.
K 6385

7. Lease Name or Unit Agreement Name:
Dee 36 SE State

7. Well No.
#6

8. Pool name or Wildcat
Dagger Draw Upper Penn, N.

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input checked="" type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Propose to Temporarily Abandon this well for future use in secondary recovery efforts as follows:

Set CIBP at 7650'. Cap with 35' cement.

Load hole with 2% KCL with 1 gpt corrosion inhibitor.

Pressure test casing to 500 psi and record with chart for 30 minutes.

Submit chart to OCD.

If casing fails pressure test, make decision on whether to look for holes or Plug and Abandon.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE TITLE Engineering Technician DATE May 1, 2002

Type or print name Susan Herpin Telephone No. 505-748-1471
 (This space for State use)

APPROVED BY TITLE Field Rep ID DATE MAY 1 2002
 Conditions of approval, if any: