c158

Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM	FORM APPROVED						
Budget Bure	eau No.	100	4-013				
Expires:	March	31,	1993				

_					
5.	Lease	Designation	and	Serial	No

SUNDRY NOTICES AND REPORTS ON WELLS

NM-2938

6. If Indian, Allottee or Tribe Name

Do not use this	form for proposals to di Use "APPLICATION FO	ill or to deepen R PERMIT—" f	or reentry to or such propos	a different reserv	oir.	e of Tribe Name
SUBMIT IN TRIPLICATE			7. If Unit or CA, A	Agreement Designation		
I. Type of Well		THE THIP EICA	,			
. □ Oil □ Gi			K.		8. Well Name and N	in .
2. Name of Operator	ell Other	· ·		2 4 1992	Arco Fed	
•	and Gas Corpor	ation /	Ana	D	9. API Well No.	erar #3
3. Address and Telepho		<u>ac1011</u>). C. D.	30-015-2	6998
P.O. Box	2523, Roswell,	NM 88202	-2523 🐠	D. COSEVE	10. Field and Pool,	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		Shugart Y	7-7Rvrs-Q-GB			
Sec. 23,	T18S, R31E				11. County or Parish	, State
	& 560' FEL					
NEINEI, U	Init Letter A				Eddy	NM
12. CHEC	K APPROPRIATE BOX(s) TO INDICA	TE NATURE (OF NOTICE, RE	PORT, OR OTHER	DATA
TYPE C	OF SUBMISSION			TYPE OF ACT	ION	
☐ Notic	ce of Intent		Abandonment .		Change of Pla	ns
			Recompletion	•	New Construc	tion
☐ Subs	equent Report	_	Plugging Back		Non-Routine I	racturing
		L	Casing Repair		Water Shut-Of	f
☐ Final	Abandonment Notice	<u> </u>	Altering Casing		Conversion to	•
		L	Other		Dispose Wate (Note: Report results o	T f-multiple completion on Well
12 Describe Proposed on	Completed Operations (Clearly state al	1		-l. 4'		oletion Report and Log form.)
7/27/92 7/28/92 7/29/92 7/30/92	RU & TOH w/rod RU & perfed Q 3535', pull tb Circ hole w/2% broke formation pump 14 bbls ballsealers, for balled out to 15"-1250, frac 12960# 20/40 & 2020, @ 5"-175 TP-1300, tag 2 @ 4223', hang	ueen zone g to 3510 g KCl, spo n @ 3330 f acid dn ormation h 3000, FPI ced w/1200 8640# 12, 0, @ 10"-1	', flange of 2 bbls eeding @ tbg, accorde from P-1800, I D0 gals 2/20 RCS @ 1720, @ 1 reverse s	up wellhea acid over .5 BPM, shu idized w/10 3600 to 16 SIP-1500, 0 20# XL conf 7 BPM @ 23 5"-1700, SI and out, TO	d, SION. perfs, pull t dn, bled o 000 gals 15 20, AIR-3 BPI 5"-1280, @ taining 1200 00 psi, FPIP	1 3 jts tbg, off pressure, % HCl + 18 M @ 1820 psi, 10"-1250, @ # 100 mesh, -2980, ISIP-
Signed Cath	the foregoing is true and correct A COOL OF THE PROPERTY OF STATE OFFICE USE) al, if any:	Title	Drillin	g Technicia	Date	8/17/92
	001, makes it a crime for any person ny matter within its jurisdiction.	knowingly and willfull	y to make to any depa	urtment or agency of the U	United States any false, fictitio	us or fraudulent statements