

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-015-27099
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	E-10167
7. Lease Name or Unit Agreement Name	Boyd X State
8. Well No.	3
9. Pool name or Wildcat	N. Dagger Draw Upper Penn
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3510' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

RECEIVED

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator YATES PETROLEUM CORPORATION	3. Address of Operator 105 South Fourth Street - Artesia, NM 88210
4. Well Location Unit Letter J : 1980 Feet From The South Line and 1980 Feet From The East Line Section 29 Township 19S Range 25E NMFM Eddy County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3510' GR	

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Perforations & treatment ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-27-94 - TIH w/4" casing guns. Perforated 7692-7778' w/36 .45" holes (2 SPF) as follows: 7692, 94, 96, 98, 7700, 22, 24, 26, 28, 30, 32, 34, 7764, 67, 71, 74, 76 & 7778'. TOOH w/casing guns. TIH w/packer and 2-7/8" tubing to 7851'. Unset RBP at 7851'. Moved up and set RBP at 7786'. Tested RBP to 1500 psi for 5 minutes, OK. Moved and set packer at 7754'. Acidized perforations 7764-7778'. Already broke down. Communicated. Unset packer at 7754'. Reset packer at 7711'. Acidized perforations 7722-7734'. Already broke down. Communicated. Unset packer at 7711'. Reset packer at 7560'. Tested annulus to 700 psi, OK. Acidized perforations 7692-7778' with 12300 gallons 20% NEFE acid with scale and paraffin inhibitor and ball sealers. Swabbing.
4-28-94 - Unset packer at 7560'. Drop down and unset RBP at 7786'. TOOH with 2-7/8" tubing, packer and RBP. Released to production department.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE Production Clerk

DATE April 28, 1994

TYPE OR PRINT NAME

Rusty Klein

505-748-1471
TELEPHONE NO.

(This space for State Use)

SUPERVISOR, DISTRICT II

TITLE

DATE

MAY 2 1994