CISÉ

Form 3160-5 (June 1990)

CONDITIONS OF APPROVAL, IF ANY:

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED

Budget Bureau No. 1004-0135

Expires: March 31, 1993

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclu	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log Form.) Iding estimated date of starting any proposed work. If well is
 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones PRIOR TO THIS PROPOSAL TO RECOMPLETE TO THE WILDCAT CANYON WOLFCAMP NOR DAGGER DRAW UPPER PENN NORTH POOL. MIRU. Install BOP. TOH w/ production equipment. TIH w/ CIBP to ~7200'. Set CIBP. Spot 35' Cmt Cap. (NEW PBTD @ 7165') Run GR-CBL from PBTD to FL or TOC. 	RTH POOL, THIS WELL PRODUCED FROM THE AREA RECEIV
 Install 5000 psi Lubricator. Perf Upper Wolfcamp w/ 4 SPF from 6218'-6542' (61' NET, 244 hole TIH w/ treating pkr on 2-7/8" WS & set pkr @ 6150'. Load annulus w/ 2% KCl. Acidize perfs w/ 4200 gals of 15% HCL NEFE. Overflush with 50 Bbls Max pressure 5000 psig on tubing. SI for 2 hr. Swab back load. Release & TOH w/ pkr on WS. TIH w/ production equipment & return well to production. 	2% KCL water.
 5. TIH w/ treating pkr on 2-7/8" WS & set pkr @ 6150'. 6. Load annulus w/ 2% KCl. Acidize perfs w/ 4200 gals of 15% HCL NEFE. Overflush with 50 Bbls Max pressure 5000 psig on tubing. SI for 2 hr. Swab back load. 	2% KCL water.