

Form 3160-5
(August 1999)UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
OMB No. 1004-0135
Expires November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an
abandoned well. Use Form 3160-3 (APD) for such proposals.RECEIVED
OCD - ARTESIA

SUBMIT IN TRIPLICATE - Other Instructions on reverse side

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Yates Petroleum Corporation

3a. Address

105 S. 4th Street - Artesia, NM 88210

3b. Phone No. (include area code)

505-748-1471

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

710' FSL & 1980' FEL SEC 23-T20S-R24E

5. Lease Serial No.

NM 86241

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

SCR70

8. Well Name and No.

HILLVIEW AHE #17

9. API Well No.

30-015-27214

10. Field and Pool, or Exploratory Area

DAGGER DRAW UPPER PENN, SO.

11. County or Parish, State

EDDY, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☒ Notice of Intent☐ Subsequent Report☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize☐ Deepen☐ Production (Start/Resume)☐ Water Shut-Off☐ Alter Casing☐ Fracture Treat☐ Reclamation☐ Well Integrity☐ Casing Repair☐ New Construction☐ Recomplete☐ Other☐ Change Plans☐ Plug and Abandon☒ Temporarily Abandon☐ Convert to Injection☐ Plug Back☐ Water Disposal

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomple horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operations results in a multiple completion or recomple in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

YATES PETROLEUM CORPORATION RESPECTFULLY REQUESTS PERMISSION TO TEMPORARILY ABANDON AS FOLLOWS:

1. MIRU WSU. INSTALL BOP & OTHER SAFETY EQUIPMENT AS NEEDED.

2. POH W/ 2-3/4" TUBING & PACKER. TIH TO RETREIVE RBP @ 7590' - POH.

3. MIRU WL TO RUN 7" CIBP. SET CIBP @ 7451'. DUMP 35' CEMENT ON TOP OF CIBP.

4. LOAD CASING WITH 2% KCL WATER & NU WELLHEAD.

5. NOTIFY OCD 24 HOURS IN ADVANCE SO THEY CAN WITNESS PRESSURE TEST - USING A PUMP WITH A CHART RECORDER, PRESSURE TEST CASING TO 500 PSI FOR 30 MINUTES.

6. TURN CHART IN TO MICHELLE TAYLOR SO THE 6-483 CAN BE FILED.

Form 3160-5

OCD approval conditional.

Well must meet BLM requirements and
obtain
their approval.

I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

Donna Clack

Signature

Title

Operations Technician

Date

4-1-02

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Artesia Engineer

Date

5/8/02

Conditions of approval, if any, are attached. Approver of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

CFO