	1	VM OIL CONS COMMISSION
		rawer DD
Form 3160-5 UN	ITED STATES	Priesia, Nr. FORM REQUED Buder Burgen No. 1004-0135
	NT OF THE INTERIOR	
BUREAU OF	LAND MANAGEMENT	Expires: March 31, 1993 5. Lease Designation and Serial No.
		NM 0452760
<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals		6. If Indian, Allottee or Tribe Name
	rill or to deepen or reentry to a different reservoir. R PERMIT—'' for such proposals	
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
		NM 88495
2. Name of Operator		8. Well Name and No. Preston Fed. Wells#9
Conoco, Inc.		Preston Fed. Wells #C/
3. Address and Telephone No.		30-015-271-2
10 Desta Dr. Ste 100W, Midland, TX 79705		10. Field and Pool, or Exploratory Area
4 Location of Well (Footage, Sec., T., R., M., or Survey Description)		South Dagger Draw
Secs. 34 & 35, T-205, R-24E		11. County or Parish, State
Sec. 34, T-20-1/25, R-24E		Eddy
CHECK APPROPRIATE BOX	s) TO INDICATE NATURE OF NOTICE, REPOR	
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent		Change of Plans
	Recompletion	
Subsequent Report	Plugging Back	Non-Routine Fracturing
	Casing Repair	Water Shut-Off
Final Abandonment Notice	Atoring Casing X Other Surface Commingling	Conversion to Injection
	Ott-Lease Storage	Dispose Water (Note: Report results of multiple completion on Wester
13. Describe Proposed or Completed Operations (Clearly state a	pertinent details, and give pertinent dates, including estimated date of starting	Completion or Recompletion Report and Los (orm)
give subsurface locations and measured and true vertice	al depths for all markers and zones pertinent to this work.)*	any proposed work. If wen is directionally orther
Conoco requests approval for su production from the South Dagge wells:	urface commingling and off-lease stora er Draw Upper Pennsylvanian Pool only	ge of Cisto Canyon oil from the following
Preston 35N Fed. #8 Preston 35N Fed. #9 Preston Fed. #1 Preston Fed. #10 Preston Fed. #5 Preston Fed. #3 Preston Fed. #4		
Surface commingling and off-lea facility diagram.	se storage will be subject to the at	tached data, map, and
	015 the	1 min fritter
	C. wy	
	Sunt	
14. [ hereby certain that the foregoing is true and correct	Sunt	` 
14. [ hereby certain that the foregoing is true and correct Signed		
( build an		21_ Date 12/1/93
Signed		21_ Date 12/1/93
Signed		
Signed		<u>Dr Date 12/1/93</u>