

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-015-27768
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	E-5136
7. Lease Name or Unit Agreement Name	Devon State
8. Well No.	1
9. Pool name or Wildcat	E. Millman-Q-GR-SA
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3400 GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐ RECEIVED
2. Name of Operator
SDX RESOURCES, INC.
3. Address of Operator
P. O. BOX 5061, MIDLAND, TX 79704
4. Well Location
Unit Letter E : 1650 Feet From The North ARTESIA LINE 1650 Feet From The West Line
Section 23 Township 19-S Range 28-E NMPM EDDY County EDDY

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☒ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-21-94 Spud well. Drill 395' of 12 1/4" hole. Run 8 5/8", 24#, J-55 csg to 392'. Cement with 350 sx Class "C" cement. Circulate 75 sx. WOC 18 hours. Test csg and BOP: 1,000# for 30 minutes and held okay. Drilled 7 7/8" hole to 2755' TD.
2-28-94 Ran LDT-CNL-GR & DLL-GR open hole logs.
Ran 83 jts 5 1/2", J-55, 15.5# csg to 2752'. Cement with 350 sx 50/50 POZ and 435 sx "Lite". Circulated 35 sx cement.
5-06-94 Tag PBTD at 2701'. Ran PDC-GR log and perforate 1 spf 26 holes: 2200, 01, 03, 14, 26, 30, 34, 48, 72, 90, 95, 2306, 10, 16, 24, 56, 66, 72, 81, 84, 2412, 16, 26, 80, 90, 96. Acidize with 3000 gal 15% NEFE. Frac with 1485 bbls X/L Borate gel and 160,000# of 12/20 sand. Clean well out to 2701'. Land tbg off at 2572', run rods and pump. Begin pumping back load.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Barbara E. Wickham TITLE Prod. Analyst DATE 05-20-94
TYPE OR PRINT NAME Barbara E. Wickham TELEPHONE NO. 685-1761

(This space for State Use)

APPROVED BY Randy TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: