

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Ent Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-28372
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Tackitt AOT
8. Well No. 3
9. Pool name or Wildcat Dagger Draw Upper Penn, North

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South 4th St., Artesia, NM 88210	4. Well Location Unit Letter 0 : 660 Feet From The South Line and 1980 Feet From The East Line Section 28 Township 19S Range 25E NMPM Eddy County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3481' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: Perforate & acidize <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-17-95 - Swabbed. Acidized perforations 7762-7768' with 1000 gallons 20% NEFE acid. Unset packer at 7660'. TOOH with tubing and packer. Rigged up wireline. TIH with 4" casing guns and perforated 7624-7680' w/23 .52" holes (1 SPF) as follows: 7624, 32, 34, 36, 38, 40, 42, 44, 46, 48, 50, 52, 54, 56, 58, 60, 62, 64, 70, 72, 74, 78 & 7680'. TOOH with 4" casing guns and rigged down wireline. TIH w/RBP, packer and tubing. Set RBP at 7722'. Tested RBP to 1000 psi, OK. Spotted 2 bbls of 20% acid across perforations 7624-7680'. Moved up and set packer at 7568'. Tested annulus to 500 psi OK. Acidized perforations 7624-7680' with 2500 gallons 20% NEFE acid and ball sealers. Unset packer at 7568'. Knocked balls off perforations. Moved up and set packer at 7568'. Acidized perforations 7624-7680' with 20000 gallons 20% NEFE gelled acid and ball sealers. Swabbing.

5-18-95 - Swabbed. Unset packer at 7568'. Unset RBP at 7722'. TOOH with tubing, packer and RBP. Released well to production department.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE 5-19-95  
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use) ORIGINAL SIGNED BY TIM W. GUM  
DISTRICT II SUPERVISOR

APPROVED BY

TITLE

DATE

MAY 30 1995

CONDITIONS OF APPROVAL, IF ANY: