Submit 3 Copies to Appropriate District Office	State of New Mexico Energy, erals and Natural Resources Department		Form C-103 Revised 1-1-89		ctsf
DISTRICT I P.O. Box 1980, Hobba, NM 88240	OIL CONSERVATION DIVISION		WELL API NO.		
DISTRICT II Santa Fe. New Mexico 87504-2088		30-015-28412			
P.O. Drawer DD, Artesia, NM \$8210 DISTRICT III			5. Indicate Type of Lease ST	ATE	<u>x</u>
1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease N	la.	
SUNDRY NOTICES AND REPORTS ON WELLS ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name		
I. Type of Well: OIL OIL OAS WELL X WELL OTHER			Thomas AJJ		
2. Name of Operator YATES PETROLEUM CORPORATION			8. Well Na. 6		
3. Address of Operator			9. Pool name or Wildcat		
105 South 4th St., Artesia, NM 88210 4. Well Location			Dagger Draw Upp	er Penn, Nor	<u>th</u>
Unit Letter :198	30 Feet From The South	Line and660	Feet From The	East	Line
Section 8	Township 19S Rar		NMPM Eddy	Coun	ty
	10. Elevation (Show whether 1 3535				
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data					
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					<b></b>
		REMEDIAL WORK		ING CASING	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING				AND ABANDONMEN	тЦ
PULL OR ALTER CASING					
OTHER:	[]	OTHER: Perfora	te and acidize		X
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.					
Installed tubinghead and tubing. Drilled drill collars and bit 2% KCL water. Test c with logging tools. 6-1-95 - TIH with 4" 7759, 64, 74, 76, 78, 20, 22 & 7824'. TIH 7759-7824' with 2500 dropped down thru per Acidized perforations Swabbed. Unset packe <u>6-2-95 - TOOH with tu</u>	ation, set and tested a and BOP. Tested casing out DV tool at 6102'. . TIH with bit, scrape asing to 2000 psi. TOO Ran CBL/CCL/GR log. TO casing gun and perfora 80, 82, 84, 86, 88, 90 with packer and tubing. gallons 20% NEFE acid a forations to knock ball 7759-7824' with 20000 r and start out of hole bing and packer. Relea	to 1800 psi. Circulate casis ar and tubing to Wh with 2-7/8" OOH with loggin ated 7759-7824' , 92, 94, 96, Set packer a and ball sealer as off. Pulled gallons gelled ased well to pr	TIH with bit, ding clean. TOOH of 8178'. Display tubing, scraper of the scrape of	rill collars with tubing, ce casing wi and bit. TH as tollows: , 14, 16, 18 ed perforation at 7700 and cker at 7700	th H ons d
I nereby certify that the information above is the	The second	<u>Production</u> (		e6-6-95	
SKONATURE THE RUSTY KLEI	*	£		ephoneno, 505/74	<b>8-1</b> 471
(This space for State Use) ORIGINAL	Signed by tim W. Gue			JUN 📅 7 1	995
APPROVED BY DISTRICT	II SUPERVISOR	<u> </u>	DAT		
CONDITIONS OF AFFROVAL, IF ANY:					