				CISIC
Form 3160-5 June 1990)	UNITED S DEPARTMENT OF BUREAU OF LAND	THE INTERIOR 🚽 🗍	011 C 1754 Ct 11 18: 10:2534	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993
	BOREAU OF EAND	MANAOEMENT		5. Lease Designation and Serial No. NM-1372
Do not use this form	UNDRY NOTICES AND for proposals to drill or to "APPLICATION FOR PEF	to deepen or reentry to a	different reservoir.	6. If Indian, Allottee or Tribe Name
1. Type of Well	SUBMIT IN T		PECENTE	7. If Unit or CA, Agreement Designation
2. Name of Operator	Other		UCD ARTESIA	. Well Name and No. Warren ANW Federal #4
	UM CORPORATION	(505) 748	1471) July 1	API Well No.
3. Address and Telephone No.	St Artoola NM 8	2210		30-015-28604
	St., Artesia, NM 88 Sec., T., R., M., or Survey Description			0. Field and Pool, or Exploratory Area
	9' FEL of Section 9-		SESE)	agger Draw Upper Penn, N 1. County or Parish, State
CHECK AF	PROPRIATE BOX(s) TO			Eddy Co., NM
TYPE OF SU				, ON OTHEN DATA
			TYPE OF ACTION	<u> </u>
L_J Notice of In	lent	Recompletion		Change of Plans
X Subsequent	Report	Plugging Back		Non-Routine Fracturing
		Casing Repair		Water Shut-Off
L Final Aband	Ionment Notice	Altering Casing X Other Perfora	te & acidize	Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
13. Describe Proposed or Comple	eted Operations (Clearly state all pertine is and measured and true vertical depth	nt details, and give pertinent dates, incl	uding estimated date of starting an	y proposed work. If well is directionally diilled,
10-28-97 - Clea Nippled up BOP Ran CBL/GR/CCL Shut down for n	aned location, set a . Rigged up wirelin logs. TOOH with lo	and tested anchors. ne. TIH with loggi ogging tools and ri	Moved in and r ng tools and tag gged down wireli	ne. TIH with tubing.
wireline. TIH	with 4" casing guns	s and perforated 77	78-7810' w/20 .4	2" holes (1 SPF -
paker at 7720' Unset packer.an perforations 77	nd ran down thru pei 778-7810' with 20000	tions 7778-7810' wi cfs to knock balls) gallons 20% gelle	th 2000 gallons off. Reset pack d HCL acid. Swa	20% gelled HCL acid. er. Re-acidized bbing.
department.	eased packer. TOOH	with tubing and pa	cker. Reteased	TED FOR RECOMD
			N	DV 0 7 1997
\sim		s∉ rRC		
14. I hereby certify that the fore	going is the and correct			
Signed 7 USU	Fl plin	Operations '	'echnician	
(This space for Federal or 3	state office use)			
Approved by		Title		Date

*See Instruction on Reverse Side