Morrow Altachment B DRILLINC-PEPORT Page 13 Yates Pet. - Hanagan "APL" Fed Com #1 (Unit G) 31-195-30E Eddy Co.,NM \* 3 17 4 AM 2200' 17 2200' 3 5 AM 6 AM 2200' 3 18 Total recovered 0 bbls oil and 70 bbls water. DC \$10,525 Continued to swab/flow as follows: 11-12-95 MCF TIME FL SR SR BW Slight Started to make gas and 7 AM 2000' 2 16 unload fluid 60# - 3/4" 12 Slight Burn 8 AM 80# - 3/4" 10 Fair Burn 9 AM 50# - 3/4" 5 Fair Burn 10 AM Burn/Rig up swab. IFL ' 201 - 3/4" 2 Fair 11 AM 10000' 10,000' 2 10 Fair Burn 12 PM 20-25' flare 200# - 1/4" 313 1 PM 20-25' flare 2 PM 190# - 1/4\* 298 190# - 1/4" 20-25' flare 298 3 PM 20-25' flare 190# - 1/4" 298 **4** PM 20-25' flare 5 PM 190# - 1/4" 298 Shut down. Daily recovery 0 BO + 55 BW. Total recovered 0 BO + 125 BW. SITP 2500#. Bled down to 80# in 60 mins. Did not unload fluid. Installed 1/4" choke. had a strong mist. Opened 11-13-95 up on a 3/4" choke. Bled down to 15 psi. IFL 10000". Continued to swab/flow as follows: TIME FL 🕴 SR BW MCF 80# - 3/4" Good Install 1/4" choke 8 AM 130# - 1/4" Str mist Install 3/4" choke. 9 AM Bled down. Rig up swab. 10 Good 10000' 10 AM 2  $190 \ddagger - 1/4"$ 20-25' flare 298 11 AM 190# - 1/4" 20-25' flare 298 12 PM 20-25' flare 190# - 1/4" 298 1 PM 20-25' flare 298 190# - 1/4" 2 PM 20-25' flare 190# - 1/4" 298 3 PM 20-25' flare 4 PM 190# - 1/4" 5 PM 190# - 1/4" 298 20-25' flare 298 Shut down. Daily recovery 0 BO + 10 BW. Total recovery 0 BO + 135 BW. Moving to Strawn. DC \$2125 10 AM WATER ANALYSIS: 11-12-95 Spec Gravity 1.025 @ 74 Resistivity .095 @ 75 6.55 Sulfate 976 pH Tot Hardness 9762 Iron 400 Bicarbonate 2678 Calcium 1953 Sod Chloride 38,508 1185 Magnesium Tot Diss Sol 53,262 23,409 Chloride Pot Chloride 1500 Sod & Pot 16,437 Iodine Nil

Morrow Test

.

1. 

"' L

DRILLI' REPORT Page 1. Yates Pet. - Hanagan "APL" Fed Com #1 (Unit G) 31-195-30E Eddy Co.,NM

\*\*\*\*\*\*\*

78 10' flare 0 4 PM  $40 \neq -1/4^{*}$ 0 0 5 PM 40# - 1/4" 0 78 10' flare Prep to frac with 30,000#. THIS AM - Overnight SITP 1800#. Bled to 0 in 30 mins. DC \$5325 SITP 1800#. Bled down to 0 psi in 30 mins. Rig up 15K 11-7-95 tree saver. Tested annulus. Annulus would not test. Rig down 15K test saver. Nippled down tree. Reset packer. Tested annulus. Annulus would not test. Nippled up BOP. Unset packer at 11,017'. TOH with 2-7/8" N-80 tubing and packer. Shut down. Prep to TIH with Uni VI 10K packer and hydrotest tubing in hole. Will frac on Tuesday at 3 PM. DC \$2475 11-8-95 TIH with packer, Uni VI 10K with 1.81 profile nipple and on/off tool and 2-7/8" N-80 tubing (hydrotest tubing in hole - test tubing to 8000 psi, found 3 collar leaks). Set packer at 11,017'. Tested annulus to 4000 psi for 10 mins, OK. Nippled down BOP and installed tree. Swabbed tubing. FL down to 9500'. Recovered 55 bbls water. Rig down swab. Rig up 15K tree saver. Frac'd perfs 11,491-11,496' down 2-7/8" N-80 tubing with 30000 gals 300 Medallion frac 4000 + 30,0001 20/40 Premium AC frac "PR" Black. Max 9765#, Avg 9325# at 16.1 BPM. ISDP 5577#, 5 mins 5010#, 10 mins 4853#, 15 mins 4843#. TLTR 618 bbls. Max sand conc 2.5 ppg. Rig down tree saver. Left well shut in for 6 hours. Flowed well back as follows: TIME PSI/CHOKE BW MCF 4000# - 8/64" 3200# - 8/64" CO2 12 AM 50 1 AM 50 CO2 little sand 2 AM 1900# - 12/64" 50 CO2 little sand 1400# - 12/64" no sand 3 AM 40 CO2 1000# - 12/64" CO2 no sand 30 4 AM 600# - 16/64" CO2 no sand 5 AM 20 500# - 16/64" CO2 no sand 6 AM 20 Total recovered 0 BO + 260 BW. Load left 358 bbls. DC \$52,225 11-9-95 Continued to flow well as follows: TIME PSI/CHOKE BW MCF too wet to burn/no sand 490# - 24/64" 7 AM 10 CO2 8 AM 380# - 24/64" 10 CO2 too wet to burn/no sand  $100 \ddagger - 1/2"$ too wet to burn/no sand 9 AM 15 CO2 10 AM 35# - 3/4" 10 CO2 too wet to burn/no sand 20# - 3/4" 15 CO2 too wet to burn/no sand 11 AM 20# - 3/4" 10 CO2 too wet to burn/no sand 12 PM Daily recovery 0 BO + 70 BW. Total recovery 0 BO + 330 BW. Load left 288 bbls. Nippled down tree and nippled up BOP. Unset packer at 11,017'. TOH with 2-7/8" N-80 tubing and Uni VI 10K packer. Started TIH with retrieving tool and 2-7/8" N-80 tubing. Shut down. Prep to finish TIH and retrieve Uni VI RBP at 11,621'. DC \$3175 Continued to TIH with retrieving tool and 2-7/8" N-80 11-10-95 tubing to 11,560'. Tag sand at 11,560'. Rig up and wash sand from 11,560-11,621'. Unset RBP at 11,621'. TOH with 2-7/8" N-80 tubing and RBP. TIH with on/off tool and 2-7/8" N-80 tubing to 11,686'. Latch on to packer at 11,686'. Unset packer 11,686'. TOH with 2-7/8" N-80 tubing and packer. TIH with retrieving tool and 2-7/8" N-80 tubing. Shut down. Prep to continue TOH with retrieving tool and 2-7/8" N-80 tubing to pull RBP; then run packer and swab in Morrow. DC \$3025 Continued TIH with retrieving tool and 2-7/8" N-80 tubing 11-11-95 to 11,750'. Washed sand from 11,750-11,812'. Latched onto RBP at 11,812'. Unset RBP at 11,812'. Started TOH with 2-7/8" N-80 tubing and RBP. Shut down because of high winds. Continued working at 6 PM 11-10-95. TOH with 2-7/8" N-80 tubing and RBP. TIH with packer (Uni VI 10K with 1.81" profile nipple and on/off tool) and 2-7/8" N-80 tubing. Set packer at 11,012'. Tested annulus to 3000 psi for 10 mins, OK. Nippied down BOP and installed tree. Rigged up swab. Swabbed as follows: TIME FL SR SR RW 3 AM 2000' 3 18

DRILLING REPORT Page 1 Yates Fet. - Hanagan "APL" Fed Com #1 (Unit G) 31-195-30E Eddy Co.,NM

psi for 10 mins,OK. Unset packer at 11,600. TOH with 2-7/8 N-80 and packer. Shut down. Prep to finish TOH with 2-7/8" N-80 tubing and packer, then TIH with Uni VI

11-2-95

packer and acidize with 100 gals acid and N2. DC \$8425 Finished TOH with 2-7/8" N-80 tubing and Uni V packer. TIH with Uni VI (10K) packer with 1.81 profile nipple and on/off tool and 2-7/8" N-80 tubing. Set packer at 11,017'. Nippled down BOP and nippled up tree. Tested annulus to 2000 psi, OK. Rigged up swab. Swabbed tubing fluid level down to 11,000'. Recovered 62 bbls. Rigged up tree\_saver. Rigged up and acidized perfs 11,491-11496 with 1000 gals 7-1/2% NEFE Morrow type acid with 1000 SCF/bbl N2 and 10 balls. Broke down 3200 psi. Avg 5400 psi @ 4.5 BPM. Ball action good. ISDP 5000 psi, 5 mins 4900 psi, 10 mins 4800 psi, 15 mins 4800 psi. Total load to recover 70 bbls. Rigged down tree saver. Rigged up and flow/swab with the following results: PSI/CHOKE TIME OIL WATER GAS 2800# - 8/64" 7 PM N2 5 0 B PM 1100# - 12/64\* 0 10 N2 9 PM 100# - 16/64" 0 5 N2 0 - 3/4" 10 PM slight burn 0 35 9800-SN 2 runs slight burn 11 PM 0 7 12 AM SN l run 0 0 slight burn 32, 5-10' flre 56, 10-15' flre 101, 10-15' flre 105, 10-15' flre  $80 \ddagger - 1/8"$ 1 MA 0 0 2 AM 150# - 1/8" Ω 0 280# - 1/8" 3 AM 0 0 290# - 1/8" 4 AM 0 0 105, 10-15' flre 290# - 1/8" 5 AM 0 0 108, 10-15' flre 6 AM 300 - 1/8" 0 0 Total recovered 0 bbls oil and 62 bbls water. Load left 8 bbls. At 8:00 AM Thursday flowing 340 psi on 1/8" choke = 122 MCFD with pressure increasing. prep to swab/flow well. DC \$13,005 Continued to swab/flow as follows: PSI/CHOKE SR BO BW TIME MCF 10-15' flare 7 AM 320# - 1/8\* 0 115 0  $340 \pm - 1/8$ " 10-15' flare 8 AM 0... ÷ 0 122 28 9 AM 1000'-SN 2 7 10-15' flare Slt Put on 1/4" choke - 20 psi = 48 MCF 10 AM  $40\frac{1}{2} - 1/4"$  0 0 77 10-15' flare 45# - 1/4" 10-15' flare 11 AM 85 0 Ω 12 PM 45 = 1/410-15' flare 0 85 0 45# - 1/4" 10-15' flare 1 PM 0 0 85 Bled down. Rig up swab. 2 PM 10200'-SN 1 21 4 Slt 10-15' flare Put on 1/4" choke,  $30\ddagger = 63$  MCF 3 PM 45# - 1/4" 85 10-15' flare 0 0 45# - 1/4" 4 PM 0 0 85 10-15' flare 5 PM 45# - 1/4" 85 10-15' flare 0 0 Daily recovery trace of oil and 11 bbls water. Total recovery - trace oil and 73 bbls water. 3 bbls over load. Shut down. Plan to frac on Monday. DC \$1525 2:00 PM WATER ANALYSIS: 11-2-95 Spec Gravity 1.065 @ 65 Resistivity .035 @ 75 рH 4.2 Sulfate 2230 Ìron 160 Total Hard 3756 Calcium 25540 Bicarbonate 69 Magnesium -14603 Sod Chlor 123540 Chloride 75100 Tot Diss Sol 145984 K+ 1200 H2S Nil SITP 1150#. Bled down to 0 psi in 25 mins. TIH with thru tubing guns. Perforated 4 SPF with 21 - .27" holes as follows: 11,491-11,496'. TOH with thry tubing guns. Flowed as follows: TIME TP/CHOKE BO BW MCF 11 AM 20# - 1/4\* 0 0 48 10' flare 10' flare 12 P.i 30 = 1/40 0 63 Perf with thru tubing guns, left well flowing  $40\# - 1/4^{\#} = 0$  0 78 10' flare 1 PM 40# - 1/4\* 2 PM 40# - 1/4" 3 PM 0 0 78 10' flare

11-3-95

11-4-6-95

Monow

REPORT

DRILL

,

· - ·

.

Page \_\_\_\_\_ Yates Pet. - Hanagan "APL" Fed Com #1 (Unit G) 31-195-30E Eddy Co.,NM

	K+ 1000						
10-30-95	SITP 2200 psi. Bl	ed down to	) 15 psi in 50	mins. Rigged up			
			1000'. Contin	ued to swab/flow			
	with the following results: TIME FL #SR OIL WATER GAS 8 AM 5000' 0 10 good, 15-20' flre						
	8 AM 5000' 9 AM 8000'	2 0		5-20' flre			
	10 AM SN	2 0		-20' flre			
	11 AM 130# - 1/4"			20' flre			
	Noon 130# - 1/4"		0 210, 15-	-20' flre			
	1 PM 130# - 1/4"		0 210, 15-	20' flre			
	2 PM 130# - 1/4"		0 210, 15-	20' flre			
	3 PM 130# - 1/4" 4 PM 130# - 1/4"		0 210, 15- 0 210, 15-	-20' flre -20' flre			
	5 PM 130# - 1/4"			-20' flre			
	Daily recovered 0	bbls oil a	and 32 bbls wa	iter. Total			
	recovered 0 bbls c	oil and 630	) bbls water,	32 bbls overload.			
			is estimated.				
	WATER ANALYSIS: 1						
	Sp. Gravity 1.02 pH 6.55		resistivity	.085 🖲 75 150			
	pH 6.55 Sulfate 68		Calcium	2732			
	Tot Hardness 10,7		Magnesium	948			
	Bicaronates 1690		Chloride	25,360			
	CALC 41,7		Sod & Pot	16,431			
	Tot Diss Sol 54,2	281 1	125	Nil			
	K+ 1500						
10-31-95	SITP 2300 psi. BI						
	swab. Initial fluwell with the foll			nued to swad/flow			
		-	WATER GAS				
	8 AM 9000' 1			15-20' flre			
	9 AM SN 2		boop 8	15-20' flre			
	10 AM 120 $= 1/$		0 195, 1	15-20' flre			
	11 AM 120# - 1/			15-20' flre			
	Noon 120# - 1/ Opened up, bled do		0 195, 1 ed up swab.	5-20' flre			
	1 PM 10,200-SN 2	2 28	· · · · · · · · · · · · · · · · · · ·	15-20' flre			
	2 AM 120# - 1/			15-20' flre			
	3 PM 120# - 1/		0 210, 1	15-20' flre			
	Daily recovered 1	bbl oil ar	nd 21 bbls wat	er. Total			
	recovered 1 bbl oi						
	Flow test - 120 ps						
	NOTE: Recovery is #3. DC \$1525		. prep to ma	ove to Morrow zone			
		AM 10-3	0-95 9 AM				
	Sp. Gravity 1	.025 @ 76		8 2 74			
		095 @ 75		ę 75			
		i.35 .50	6.55				
		i3	125	4 · · · · · ·			
		341 -	1955				
		.0,732	9775				
		.185	1188				
	Bicarbonate 1						
		762	1717	-			
	Chloride 2	5,360	23,45				
	Chloride 2 CALC 4	5,360 1,717	23,45	14			
	Chloride 2 CALC 4 Sod & Pot 1	5,360 1,717 6,464	23,45 38,58 15,37	14 /1			
	Chloride2CALC4Sod & Pot1Tot Dis Solids5H2Sm	5,360 1,717 6,464 4,381 11	23,45	14 /1			
	Chloride2CALC4Sod & Pot1Tot Dis Solids5H2SmK+1	5,360 1,717 6,464 4,381 11 500	23,45 38,58 15,37 50,38 nil 1500	4 1 37			
11-1-95	Chloride2CALC4Sod & Pot1Tot Dis Solids5H2SmK+1SITP 2350 psi.Ri	5,360 1,717 6,464 4,381 11 500 .gged up sl	23,45 38,58 15,37 50,38 nil 1500 ickline and a	4 1 7 set standing valve			
11-1-95	Chloride 2 CALC 4 Sod & Pot 1 Tot Dis Solids 5 H2S m K+ 1 SITP 2350 psi. <u>Ri</u> in packer at 11,68	5,360 1,717 6,464 4,381 11 500 gged up sl	23,45 38,58 15,37 50,38 nil 1500 ickline_and_s lown_tubing	4 1 7 get standing valve Loaded tubing with			
11-1-95	Chloride 2 CALC 4 Sod & Pot 1 Tot Dis Solids 5 H2S m K+ 1 SITP 2350 psi. <u>Ri</u> in_packer at 11,68 23_KCL water. Get	5,360 1,717 6,464 4,381 11 500 gged up sl 6. Bled d	23,45 38,58 15,37 50,38 nil 1500 ickline_and_s ickline_and_s f tool, Nipp	14 21 27 26t standing valve Loaded tubing with 201e down tree.			
11-1-95	Chloride 2 CALC 4 Sod & Pot 1 Tot Dis Solids 5 H2S m K+ 1 SITP 2350 psi. <u>Ri</u> in_packer at 11,68 2% KCL water. Get Nippled up BOP. T	5,360 1,717 6,464 4,381 11 500 .gged up sl 6. Bled d off on/of OH with 2-	23,49 38,58 15,37 50,38 nil 1500 ickline_and_s ickline_and_s f tool. Nipp 7/8" N-80 tub	4 7 27 Loaded tubing with ole down tree. bing. Rigged up			
11-1-95	Chloride 2 CALC 4 Sod & Pot 1 Tot Dis Solids 5 H2S n K+ 1 SITP 2350 psi. Ri in_packer at 11,68 2% KCL water. Get Nippled up BOP. T wireline. TIH wit place and perforat	5,360 1,717 6,464 4,381 500 gged up sl 66. Bled d off on/of OH with 2- h 4" casir e Morrow 2	23,45 38,58 15,37 50,38 nil 1500 ickline and s lown tubing. f tool. Nipp 7/8" N-80 tuk g guns. Corr one #3 (2 SPE	tet standing valve Loaded tubing with ble down tree, bing. Rigged up celated guns into - 60 deg phasing			
11-1-95	Chloride 2 CALC 4 Sod & Pot 1 Tot Dis Solids 5 H2S n K+ 1 SITP 2350 psi. Ri in packer at 11,68 2% KCL water. Get Nippled up BOP. T wireline. TIH wit place and perforat with KA42" hol	5,360 1,717 6,464 4,381 500 gged up sl 6. Bled d off on/of OH with 2- h 4" casir Morrow 2 es as foll	23,45 38,58 15,37 50,38 nil 1500 ickline and s lown tubing. f tool. Nipp 7/8" N-80 tub g guns. Corr one #3 (2 SPE ows: 11,491	24 27 27 Loaded tubing with ole down tree, oing. Rigged up celated guns into 7 - 60 deg phasing -11.496'. TOU with			
11-1-95	Chloride 2 CALC 4 Sod & Pot 1 Tot Dis Solids 5 H2S n K+ 1 SITP 2350 psi. <u>Ri</u> in_packer at 11,68 2% KCL water. Get Nippled up BOP. T wireline. TIH wit place and perforat with M242" hol 4" casing guns and	5,360 1,717 6,464 4,381 11 500 9ged up sl 6. Bled c off on/of OH with 2- th 4" casir e Morrow 2 es as foll l rigged do	23,45 38,55 15,37 50,38 nil 1500 ickline and s lown tubing. f tool. Nipp 7/8" N-80 tub ig guns. Corr one #3 (2 SPE ows: 11,491- wn wireline.	the standing value Loaded tubing with ble down tree, bing. Rigged up related guns into - 60 deg phasing' 11,496'. TOH with TIH with RBP			
11-1-95	Chloride 2 CALC 4 Sod & Pot 1 Tot Dis Solids 5 H2S n K+ 1 SITP 2350 psi. <u>Ri</u> in_packer at 11,68 2% KCL water. Get Nippled up BOP. T wireline. TIH wit place and perforat with M242" hol 4" casing guns and (10K), packer and	5,360 1,717 6,464 4,381 11 500 9ged up sl 6. Bled c off on/of OH with 2- th 4" casir e Morrow 2 es as foll rigged do 2-7/8" N-E	23,45 38,56 15,37 50,38 nil 1500 ickline and s lown tubing. f tool. Nipp 7/8" N-80 tubing one \$3 (2 SPF ows: 11,491- ows: 11,491- own wireline. 0 tubing. Se	the standing value Loaded tubing with ble down tree, bing. Rigged up related guns into - 60 deg phasing' 11,496'. TOH with TIH with RBP			

Mom DRILLI REPORT Page 5 Yates Pet. - Hanagan "APL" Fed Com #1 (Unit G).31-195-30E Eddy Co.,NM

	Sulfate	191	Calcium	8038
	Tot Hardness		Magnesium	1163
	Bicarbonate		Chloride	114,807
	CALC	188,857	Sod & Pot	87,168 none
10 35 05	Tot Diss Sol		H2S	none
10-25-95 10-26-95	Prep to frac I	Morrow with 3	0.000 gals and	30,000 <b>#</b> sand at
10-20-33	10:00 AM Thur			
10-27-95	Rig down swab	. Rig up 15K	tree saver.	Rig up and frac
	perfs 11,770-	11,778' with	35,867 gals of	300 Medallion frac
	4000 and 3100	0# 20/40 AC f	rac Premium bl	ack sand. Avg
				8#, 10 mins 3968#,
	15 mins 3900#	. Max sand J	Shut in for 6	598 bbls. Shut hours. Flow back
	in. Rig down well with the			HOULS. FIOW DACK
	TIME TP/CHO		MCF	
	10 PM 3000#	- 1/8" 30	0 gelbro	ke
	11 PM 2300#	- 1/4" 40	0 no sand	
	12 AM 7700	- 1/4" 40 - 16/64" 60 - 16/64" 50	CO2 no sand	
	1 AM 1300	- 16/64" 60	CO2 little	-
	3 AM 900¥ A NM 7504	- 16/64" 50 - 16/64" 50	CO2 little CO2 little	sand
	5 AM 650#	- 16/64" 50	CO2 no sand	
		- 16/64" 50		
	Total recover	ed 0 bbls oil	+ 420 bbls wa	ter. Load left 178
				ed, flowing to pit
	not a frac ta			leveles manulas.
10-28-95			WATER GAS	lowing results:
		16/64" 0	50 CO2 - r	io sand
	8 AM 150# -		30 CO2 - r	
	9 AM 50‡ -	3/4" 0	15 CO2 - r 20 CO2 - r	
	10 AM 50 <b>#</b> -	3/4" 0	20 CO2 - r	io sand
	11 AM 40# -	3/4" 0	10 <b>sl</b> - no	
	Nec- 204	3/48 0		ttent flr
	Noon 30# - 1 PM 22# -	the second se		iter flre
	Installed 1/4			
	2 PM 70# -	· · · ·		0-15' flre
	3 PM 70‡ -	1/4" 0	0 122 - 1	0-15' flre
	4 PM 70# -			0-15' flre
			and 131 bbls	
				Load left 47 bbls mate. DC \$1725
10-29-95	SITP 1500 pai	. Bled down	to 0 psi in 50	mins. Rigged up
				nued to flow/swab
	with the foll	owing results	3:	
	TIME FL	SR OIL	WATER GAS	
	8 AM 3000' 9 AM 5500'-	900'3 0		5-20' flre
	9 AM 5500'- 10 AM 4000'			15-20' flre
		scat 1 0		5-20' flre
	Noon 9000'	scat 2 0	10 good, 1	5-20' flre
		1/4" ~ 0	0 195, 19	
	2 PM 130# -			5-20' flre
	3 PM 130# - 4 PM 130# -			5-20' flre 5-20' flre
	5 PM 130# -			5-20' flre
			and 47 bbls wa	
	recovered 0 b	bls oil and S	598 bbls water.	Load left 0
	bbls. NOTE:	Recovery is	an estimate.	Flowed and swabbed
			down. DC \$172	25
	WATER ANALYSI			115 0 75
	Sp. Gravity	1.020 @ 72 6.6	Resistivity Iron	.115 @ 75 175
	pH Sulfate	69	Calcium	2353
	Tot Hardness		Magnesium	1429
	Bicarbonate	2763	Chloride	19,603
	CALC	32,248	Sod & Pot	11,304
	Tot Diss sol	45,504	H2S	nil

- ۱مسر

٠

•

llorm DRILLI REPORT Page 1 Yates Pet. - Hanagan "APL" Fed Com #1 (Unit G) 31-19S-30E Eddy Co., NM \*\*\*\*\*\* \*\*\*\*\*\*\*\*\*\*\*\* Magnesium 91 24 157 Bicarbonate 205 13,858 Chloride 20,556 22,797 CALC 33,815 17,305 Sod & Pot 11,595 27,590 Tot Diss Solids 40,169 H2S None None 10-22-95 SITP 700 psi. Bled to 0 psi in 30 mins. Initial fluid level 9200'. First swab run recovered 0 bbls oil and 3 bbls water. Continued to swab/flow with the following results: TIME FL **F**SR OIL WATER GAS 11000' slight - burn 9 AM 2 0 6 10 AM 70# - 1/8" 28.8 5-6' flre\* 0 0 34.0 5-6' flre\* 85# - 1/8" 11 AM 0 0 95# - 1/8" 5-6' flre\* Noon 0 0 37.4 6-8' flre\* 110# - 1/8" 42.6 1 PM 0 0 130# - 1/8" 10-15' flre\* 2 PM 0 0 49.6 10-15' flre\* 140# - 1/8" 3 PM 0 0 53.0 10-15' flre\* 140# - 1/8" 4 PM 0 53.0 0 10-15' flre\* 5 PM 140# - 1/8" 0 0 53.0 \*Burn Total recovered 0 bbls oil and 68 bbls water. Load left 5 bbls. DC \$1975; CC \$48,660 WATER ANALYSIS: 9 AM 10/21 Sp. Gravity 1.050 @ 74 .075 @ 75 Resisitivity 3.3 49 ъΗ Iron 714 190 Sulfate Calcium Tot Hardness 1810 Magnesium 324 Bicarbonate 198 Chloride 34,278 29,407 CALC 56,387 Sod & Pot Tot Diss Sol 66,406 H2S none SITP 1000 psi. Bled to 0 psi in 40 mins. Initial fluid level 10,200'. First swab run recovered 0 bbls oil and 4 10-23-95 bbls water. Continued to swab/flow with the following results: OIL WATER GAS TIME **SR** FL 11,000' 9 AM 2 0 5 slight - burn 22# - 1/4" ck 51 6-8' flre\* 10 AM 0 0 221 - 1/4" ck 11 AM 6-8' flre\* 0 0 51 22# - 1/4" ck 6-8' flre\* Noon 0 0 51 \*Burn Daily recovered 0 bbls oil and 5 bbls water. Total recovered 0 bbls oil and 73 bbls water. Load left 0 bbls. DC \$1475; CC \$50,135 THIS AM: SITP 1050 psi. WATER ANALYSIS: 9 AM 10/22 Sp. Gravity 1.050 @ 73 Resisitivity .065 @ 75 рĦ 3.3 Iron 52 Š95 Sulfate Calcium 571 Tot Hardness 1905 Magnesium 116 38,087 Bicarbonate 93 Chloride CALC 62,653 Sod & Pot 32,548 Tot Diss Sol 37,227 H2S none 10-24-95 SITP 1050 psi. Bled down in 45 mins. Initial fluid level 9800'. First swab run recovered 3 bbls of distillate and 3 bbls water. Continued to swab/flow with the following results: TIME PSI/CHOKE OIL WATER GAS 9800' 1 run 11,000' 1 run 9800' 8 AM 3 3 slight 9 AM 28 2 slight, 2% distillate 20# - 1/4" 48 - 4-5' flre\* 48 - 4-5' flre\* 10 AM 0 0 20# - 1/4" 11 AM 0 0 20 = -1/448 - 4-5' flre\* Noon 0 0 \*Burn Daily recovered 3 bbls of distillate and 5 bbls water. Total recovered 3 bbls of distillate and 78 bbls water, 5 bbls overload. Prep to frac Wednesday/Thursday. DC \$1475; CC \$51,610 WATER ANALYSIS: 1st swab run 10-23-95 Sp. Gravity 1.045 @ 72 .025 @ 75 Resistivity 5.5 рH 31 iron

DRILLING ORT



Page 7 Yates Pet. - Hanagan "APL" Fed Com #1 (Unit G) 31-195-30B Eddy Co., NM

		11 0001	1	~	1	aliah+#	
	5 AM 6 AM	11,000' wait	I	v	1	slight*	
	thurn when	n pulling	g swab,	vac a	fter sw	ab run	1 3 1 - 64 70
	Total reco	overed 0	bbls of	l and	69 bbl	s water. \$11.725.	Load left 29 CC \$31,085
	WATER ANA	LYSIS:	5 PM 10/	18 1	1 PM 10	/18 3 AM	10/19
	Sp. Gravi	ty	1.015 0	66 1	.085 🖲	66 1.070	) (0.64
	Resistivi		.125 @ 1 7	75. 4	025 @ 7	5.025 5	ų 75
	pH Iron		9	1		6	
	Sulfate		172		38	196	
	Calcium		473 2266	-	530 2,949	8598 52,3	16
	Total Har Magnesium		263		6,797	7494	
	Bicarbona	te	300		57	114	
	Chloride		17,730 29,166		65,861 72,842	130, 215,	
	CALC Sod & Pot		14,361		3,808	82,1	
	Tot Diss		34,830	3	42,914	265,	601
	H2S		 700		- 00	 600	
10-20-95	K+ Continued					wing resu	lts:
20 20 33	TIME F	L	#SR	OIL W	ATER	GAS	
	7 AM 1 Burn when	1,000'	i swab.	0 Vac a	1 fter sv	slight vab run	
	8 AM 0	psi 🛙 1	/8 ck	0	0	slight	
	Daily rec	overed 0	bhls o	il and	l 1 bbls	a water. er. Load	Total left 28.
	hhla Ri	aged dow	n swab.	Load	led tubi	ing with 6	0 bbls 2% KCL
	water. D	inset pac	ker at	11.812	!'. Nip	opled down	tree ano
	installed	BOP. TO	)H_With vireline	2-//8" . TTP	' N-80 \   with 4	and	packer (UNI guns.
	Correlate	d guns j	nto pla	ce and	l perfo	rated (2 S	PF - 60 deg
	phasing)	with 18	41"	holes	as fol	lows: 11, wireline	770-11,778'. TIH with
	RRP. DAC)	cer and a	2-7/8" N	1-80 tu	ubing.	Set RBP a	t 11,812 ·
	Tested RI	3P to 200	0 psi.	OK. N	loved u	o and set	packer at
	11,716'.	NIppled	l down E	OP and Rigo	l insta led up	lled_tree. swab. Shu	Tested t down. Prep
	to swab	tubing f	luid lev	vel dov	wn to 1	0,000' and	acidize. DC
	\$5325+ C	336.410	)				lecovered 63
10-21-95	bhle R	igged up	tree sa	ver.	Tested	adn hold	1000 psi on
	annulus.	Riaged	up and	acidia	zed per	fs 11,770-	11,778' with
	1000 gal		HCL Mos	row t	ype aci D pei	d with lut 5300 psi (	0 SCF/bbl N2 4 BPM. Ball
	action n	one. IS	DP 4800	psi,	5 mins	4500 ps1,	10 mins 4230
	net. 15 1	mins 420	Dosi.	Total	load t	o recover	73 DD18.
·	followin	own tree g result	saver. B:	RIGG	ea up a	UG LIOWY S	vab with the
	TIME	FL	\$SR C	DIL WA	TER GA	S	
		4200# 300# - 1	/4" ck	0	34 0	N2	
		0#	1	0	2 0	N2	
	Rigged u	p swab.				7100' cid gas	
	4 PM 5 PM	10,000' 10,500'	2 2			light - b	ırn
	6 pM	11,000'	2			light - b	
	7 PM	11,000-S 20# - 1/	N 1 8° ck	0 0		light - bu 1.45 - bu	
					3	' lazy fl	are
	Total re	covered	0 bbls	oil an	d 62 bb	ls water.	Load left 11
	bbls. S WATER AN	hut down		10,2/5	; CC \$4	7 PM	
	Sp. Grav		1.070	e 77		1.010 @ 7	4
	рĦ		3.1 .115	<b>8</b> 75		3.3	
	Resistiv Iron	- <b>T</b> C Y	40			23	
	Sulfate		421 523			495 554	
	Calcium Tot Hard	iness	1682			1485	
· · .							

•

i, . ...

orvou

Page 6 Yates Pet. - Hanagan "APL" Fed Com #1 (Unit G) 31-195-30E Eddy Co., NM

> DETAILED CASING REPORT: TD 7-7/8" hole at 4:30 AM. 10-10-95. Ran 292 joints (12,161.28') casing, set at 140' as follows: 55 joints 5-1/2" 17# S-95 LT&C 2310.73' 220 joints 5-1/2" 17# N-80 LT&C 9146.47' 17 joints 5-1/2" 17# S-95 LT&C 702.08' Float shoe set 12,140'. Float collar set 12,097.40'. DV tool set 9207.66'. Cemented in two stages as follows: Stage I - 800 sxs Premium Lite + 5#/sx Gilsonite + .6% Halad 9 + 5% SMJ + .3% CFR-3 (yld 1.54, wt 13.5). PD 12 PM 10-13-95. Bumped plug to 1500 psi for 5 mins. Circulated thru DV tool 4 hours. Stage II - 1250 sxs Howco Lite + 5#/sx Salt + 1/4#/sx Flocele + .2% CFR-3 (yld 1.18, wt 15.6). PD 6 PM 10-13-95. Bumped plug to 4000 psi for 5 mins, float and casing held. Circulated 60 sacks. Rig released 10 PM 10-13-95.

Prep to move in service unit.

2 AM

3 AM

4 AM

wait 11,000'

wait

?ORT

DRILLING

10-17-95
Cleaned location. Set and tested anchors and markers. Made cut off on 5-1/2" casing. Moved in and rigged up pulling unit. Installed tubing head and nippled up BOP. TIH with bit, stabilizer, drill collars and 2-7/8" N-80 tubing to DV tool at 9208'. Rigged up power swivel and drilled out DV tool. Tested casing to 3000 psi for 15 mins, OK. Finished TIH to 12,075'. Circulated casing with 2% KCL water. TOH with 2-7/8" N-80 tubing, drill collars, stabilizer and bit. TIH bit, scraper and 2-7/8" N-80 tubing to 9250'. Worked scraper thru DV tool. Prep to TOH with 2-7/8" N-80 tubing and run CBL/CCL/GR. Plan to perf Morrow zone today and acidized with 2000 Wednesday. DC \$9985

10-18-95 TOH with 2-7/8" N-80 tubing, scraper and bit. Rigged up wireline. TIN with logging tool. Correlated log,ing tool into place and pressured casing to 1000 psi and run CBL/CCL/GR log from 12,071-3000'. TOH with logging tool. TIH with 4" casing guns. Correlated guns into place and perforated (2 SPF - 60 deg phasing) with 28 - .41" holes as follows: 11,872-11,878' and 11,853-11,859'. TOH with 4" casing guns and rigged down wireline. TIH with Uni VI packer with on/off tool and 1.81" profile nipple and 2-7/8" N-80 tubing to 11,812'. Shut down. Prep to acidize Morrow Zone \$1 with 2000 gals acid with N2 and balls. DC \$9375; CC \$19,360

\_Finished\_TIH\_with\_2-7/8"\_N-80\_tubing\_to\_11.907'. \_\_Rigged\_up 10-19-95 and spotted 2 bbls of 7-1/2% HCL Morrow acid across perfs 11,853-11,878' ... Moved up and set packer at .11,812' Reversed 2 bbls inside tubing. Nippled down BOP and installed tree, Loaded and tested annulus to 1000 psi, OK. Rigged up swab. Swabbed fluid level in tubing down to 10,000'. Recovered 62 bbls. Rigged down swab. Rigged up tree saver. Rigged up and acidized perfs 11,853-11,878' with 2000 gals 7-1/2% HCL Morrow type acid with 1000 SCF/bbl N2 and 45 balls. Broke down 6200 psi, avg 6200 psi @ 4 BPM. Ball action good. ISDP 5500 psi, 5 mins 5200 psi, 10 mins 5100 psi, 15 mins 5000 psi. Total load to recover 98 bbls. Rigged down tree saver. Rigged up and flow/swab\_with the following results: OIL WATER GAS #SR FL TIME 700# - 1/4" ck 0 N2 0 34 4 PM 2 0 N2 0 = 1/4 ck 0 5 PM 1600' flowed N2 1 0 22 0 6 PM 0 no recovery 0 0 10,000' 1 7 PM light plant went down 8 PM waiting on new light plant 9 PM 10,200<sup>i</sup> 10 PM 0 6 slight\* 10,800' 2 11 PM 11,000' 2 0 2 slight\* 12 AM slight\* 11,000' 1 0 1 1 AM

1

0

1

slight\*