

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

C/SF
6/

DISTRICT I
P. O. Box 1980, Hobbs, NM 88240
DISTRICT II
811 S. 1st Street, Artesia, NM 88210-2834
DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P. O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-28820
5. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
6. State Oil & Gas Lease No. 001789
7. Lease Name or Unit Agreement Name Merchant State
8. Lease No. 3
9. Pool Name or Wildcat East Millman Queen (Grayburg San Andres)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)	
1. Type of Well Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator Bass Enterprises Production Company	
3. Address of Operator P. O. Box 2760 Midland, Texas 79702-2760	
4. Well Location Lot 2 : 990' Feet From The North Line and 1560' Feet From The East Line Section 1 Township 19S Range 28E NMPM Eddy County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3385.2' GL, 3395' DF, 3396 KB	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: Add Perfs & Frac <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1) Set CIBP @ 2530' and dump bail 10' sand on top. 11/18/96
2) RIH w/ 4" casing gun loaded with 2 JSPF and 0 degree phased and perforate the following interval: 11/19/96
2300-2304' (4', 8 shots)
2376-2378' (2', 4 shots)
2422-2427' (5', 10 shots)
3) Acidized perfs with 290 gals 15% HCl acid with additives and dropped 39 1.3 SG ball sealers. 11/20/96
4) Frac'd with 60,000 gals 35# guar based gel and 232,000 lbs of 20/40 Brady sand with 700# proppet. 12/5/96
5) Clean out sand and cement to PBTD @ 2530'. 12/7/96
6) Return well to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE: Tami L. Wilber TITLE: Production Clerk DATE: 1/9/97

TYPE OR PRINT NAME: Tami L. Wilber Telephone No. (915) 683-2277

(This space for State Use)

APPROVED BY: ORIGINAL SIGNED BY TIM W. CUM TITLE: DISTRICT SUPERVISOR DATE: JAN 11 1997

CONDITIONS OF APPROVAL, IF ANY:

copy