## N.M. Oil Cons. Division 811 S. 1st Street

Form 3160-5 (June 1990)

**UNITED STATES** DEPARTMENT OF THE INTERIOR Artesia, NM 88210-2834

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

Change of Plans

New Construction

**BUREAU OF LAND MANAGEMENT** 

	LC 029387 B			
Do not use this form for proposals to drill or to	SUNDRY NOTICES AND REPORTS ON WELLS e this form for proposals to drill or to deepen or reentry to a different reservoir.  Use "APPLICATION FOR PERMIT-" for such proposals			
SUBMIT IN TRI	PLICATE 7. If Unit or CA, Agreement Designation			
1. Type of Well				
Oil Gas  Well Dother	8. Well Name and No. West Shugart '30' Federal #1			
2. Name of Operator	West Shugart '30' Federal #1			
CONCHO RESOURCES INC.	9. API Well No.			
3. Address and Telephone No.	30015-29166			
110 W. LOUISIANA STE 410; MIDLAND, TX 79701 (91	5) 683-7443 \(\sum_{\infty} \infty \i			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	Shugart Bone Spring North			
1980' FNL & 1980' FWL, SEC. 30, 18S, 31E.	5) 683-7443  10. Field and Pool, or Exploratory Area Shugart Bone Spring North  11. County or Parish, State			
	EDDY, NM			
12. CHECK APPROPRIATE BOX(s) TO INI	DICATE NATURE OF NOTICE, REPORT, OR OTHER DATA			
TYPE OF SUBMISSION	TYPE OF ACTION			

Casing Repair Water Shut-Off Altering Casing Conversion to Injection Final Abandonment Notice Other Add additional pay □ Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

Abandonment

Plugging Back

Recompletion

13. Describe Proposed or Completed Operations (Clearly state all pertinet details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markders and zones pertinent to this work.)\*

CONCHO RESOURCES INC. RESPECTFULLY REQUESTS APPROVAL TO ADD ADDITIONALBONS SPRING PAY IN THE W. SHUGART 30 FEDERAL NO. 1 WELL ACCORDING TO THE FOLLOWING PROCEDURE:

- 1. RIH & PERF BONE SPRING W/ 2 SPF @ 7802-12 (20 SHOTS).
- 2. RIH & SET RBP @ 8100'.
- 3. ACIDIZE PERFS W/ 1000 GALS 7.5% NEFEACID.
- 4. FRAC PERFS W/ 89000# 20/40# SAND.
- 5. RETURN WELL TO PRODUCTION

Notice of Intent

Subsequent Report

14. I hereby certify that the foregoing is true and correct				
Signed	Title	Production Analyst	Date	08/16/00
(This space for Federal Charle office use)	Title	PETROLEUM ENGINEER	_ Date	SEP 1 8 2000
Approved byConditions of approval, if any:				