IO. O COPIES RECEIVED	3	-]]		Form C-103		
DISTRIBUTION	1		1		Supersedes Old * C-102 and C-103		
ANTAFE	T		NEW MEXICO OIL CONSI		Effective 1-1-65		
I LE	T	-]	TTTTTT			
U.S.G.S.	1			RECEIVED	5a. Indicate Type of Lease		
LAND OFFICE	1				State X Fee		
OPERATOR	1]	JUL 2 9 1974	5. State Oil & Gas Lease No.		
			-	500 - 1074	G-7815		
(DO NOT USE THIS PO			RY NOTICES AND REPORTS ON	ACK TO A DI FFERENT RELEANDIG. H Proposals.)			
1.		,		ARTESIA, UFFICE	7. Unit Agreement Name		
OIL CAS		ļ	OTHER-				
2. Name of Operator	8, Farm or Lease Name						
Gulf Oil Corpor	Rddy AV State (NCT-A)						
3. Address of Operator				<u></u>	9, Well No.		
Box 670, Hobbs	2						
4. Location of Well	<u> </u>			······································	10. Field and Pool, or Wildcat		
I			1650 FEET FROM THE South	LINE AND 330 PEET FROM	E. Millman Q. Cbr.		
East			10N 21 TOWNSHIP 19-S	RANGE NMPM.			
THE		36611		NANGE NMEW.			
	$\overline{\Pi}$	\overline{III}	15. Elevation (Show whether	DF, RT, GR, etc.)	12. County		
ΛΙΙΙΙΙΙΙΙΙΙΙΙΙ	())	())	339	9' GL	Lea Ford -/		
16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data							
NOTI			NTENTION TO:	-	REPORT OF:		
PERFORM REMEDIAL WORK	٦		PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING		
TEMPORARILY ABANDON	Ŧ			COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT		
PULL OR ALTER CASING	ร		CHANGE PLANS	CASING TEST AND CEMENT JOB			
OTHER			[]				
V(NER				Plugged and abandoned.	•		
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed							

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1 103.

Pulled producing equipment. Set CI BP at 1660". Circulated hole with abandonment mud. Spotted 4 sacks of cement on top of BP. Cut and recovered 4-1/2" casing from 1000". Spotted 17 sack, 100' cement plug from 1050' to 950', across 4-1/2" casing stub at 1000'; 26 sack, 100' cement plug from 750' to 650'- across Yates formation; 28 sack, 100' cement plug from 300' to 200', across 8-5/8" casing shoe at 201' and 15 sack cement plug from 50' to surface. Installed dry hole marker. Plugged and abandoned July 26, 1974. Will advise when location is ready for your inspection.

م باي کرد
perel Col. 74

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED_Blanking	Area Engineer	DATE July 26, 1974
APPROVED BY	TITLE OIL AND GAS INSPECTOR	NOV 1 1974

EONDITIONS OF APPROVAL, IF ANYL