




OXY CRENDELAU STATE #1

Located at 660' FNL and 660' FWL

Section 20, Township 19 South, Range 28 East,
N.M.P.M., Eddy County, New Mexico.



P.O. Box 1786
1120 N. West County Rd.
Hobbs, New Mexico 88241
(505) 393-7316 - Office
(505) 392-3074 - Fax

W.O. Number: 0158AA - KUG #122

Survey Date: 03-22-2000

Scale: 1" = 2000'

OXY USA INC.