

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-015-29968
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	Ross IZ
8. Well No.	2
9. Pool name or Wildcat	Dagger Draw Upper Penn, North

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator YATES PETROLEUM CORPORATION	
3. Address of Operator 105 South 4th St., Artesia, NM 88210	
4. Well Location Unit Letter <u>E</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>660</u> Feet From The <u>West</u> Line Section <u>28</u> Township <u>19S</u> Range <u>25E</u> NMPM <u>Eddy</u> County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>3495' GR</u>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Perforate & acidize ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-18-98 - Cleaned location and set anchors. Moved in and rigged up pulling unit. TIH with bit, scraper and tubing. Tagged PBTD at 8204'. TOOH. Nippled up BOP. Rigged up wireline. TIH with logging tools and ran GR/CBL log. TOOH with logging tools and rigged down wireline.
2-19-98 - TIH with 2-7/8" tubing open-ended to 7800'. Pickled tubing with 500 gallons 15% HCL acid. Reversed out. TOOH with tubing. Rigged up wireline with full lubricator. TIH with 4" casing guns and perforated 7787-7796' w/18 .42" holes (2 SPF - Canyon). TOOH with casing guns and rigged down wireline & lubricator. TIH with packer and RBP. Set RBP at 7820' and packer at 7755'. Loaded annulus and tested to 500#. Swabbed. Shut well in.
2-20-98 - Swabbed. Shut well in.
2-21-98 - Bled well down. Pumped 40 bbls 2% KCL down tubing. Released packer and ran 2 joints. Released RBP. Pulled up and set RBP at 7775'. Tested RBP to 1500#. TOOH with packer. Rigged up wireline with full lubricator. TIH with 4" casing guns and perforated 7690-7761' w/35 .42" holes. TOOH with casing guns and rigged down wireline and lubricator. TIH with packer and set packer at 7640'. Acidized perforations 7690-7761'

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

CONTINUED ON NEXT PAGE:

SIGNATURE Rusty Klein TITLE Operations Technician DATE Feb. 26, 1998

TYPE OR PRINT NAME Rusty Klein

TELEPHONE NO. 505/748-1471

(This space for State Use) ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR

APPROVED BY _____ TITLE _____ DATE 4-2-98

CONDITIONS OF APPROVAL, IF ANY:

YATES PETROLEUM CORPORATION

Ross IZ #2

Section 28-T19S-R25E

Eddy County, New Mexico

SUNDRY NOTICE CONTINUED:

with 1500 gallons 20% iron control HCL acid and ball sealers. Released packer and ran down thru perforations to knock balls off. Reset packer. Loaded annulus with 500 bbls. Pressured to 500#. Re-acidized perforations 7690-7761' with 15000 gallons 20% iron control gelled acid. Swabbed & flowed.

2-22-23-98 - Flow tested. Shut well in.

2-24-98 - Rigged up wireline. TIH with static BHP bomb. TOOH. Bled well down.

Pumped 45 bbls 2% KCL down tubing. Released packer and RBP. TOOH with tools.

Nippled down manual BOP. Nippled up hydril BOP. Released well to production department.

A handwritten signature in cursive script, reading "Rusty Klean", is written over a horizontal line.

Rusty Klean

Operations Technician

February 26, 1998