## 30-015-29993

CORTU 15742 Vices 23184 Part 15472

6-9-98

Azimuthal Laterolag

HETT-SCHZ.

Comp. Neutren

200 - 8020

Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

OT CONCEDUATION DIVICION	•
DISTRICT I P.O. Box 1980, Hobbs, NM 88240  DISTRICT II P.O. Drawer DD, Artesia, NM 88210  OIL CONSERVATION DIVISION P.O. Box 2088  Santa Fe, New Mexico 87504-2088	WELL API NO. 30-015-29993
	5. Indicate Type of Lease
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410	STATE FEE X  6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS  ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name
1. Type of Well: OIL GAS WELL OTHER DRY HOLE	S.P. JOHNSON
2. Name of Operator	8. Well No.
NEARBURG PRODUCING COMPANY  3. Address of Operator	9. Pool name or Wildcat
P.O. BOX 823085, DALLAS, TEXAS 75382-3085	UNDESIGNATED WOLFCAMP
4. Well Location  Unit Letter G: 1650 Feet From The NORTH Line and 1980 Feet From The EAST Line	
Section 5 Township 20S Range 25E	NMPM EDDY County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3512 K.B.	
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: SUE	SSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT X	
PULL OR ALTER CASING CASING TEST AND C	EMENT JOB
OTHER: OTHER:	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  1. Set CIBP @ 7240'.  2. Loaded hole w/9.6#, brine based mud.  3. Spotted 25 sx plug on CIBP.  4. Set 100' Wolfcamp plug 5814 to 5714.  5. Cut and pulled 7" casing @ 5190'.  6. Spotted 50 sack plug 50' in stub @ 5240', tagged top of plug @ 5126'.  7. Spotted 50 sack Bone Springs plug 3712 to 3577'.  8. Spotted 50 sack Glorieta plug 2304 to 2169'.  9. Spotted 60 sack plug (Base of 9 5/8 @ 1157) 1107 to 944'.  10. Spotted 10 sack surace plug.  11. Set dry hole marker.	
I hereby certify that the information above is true and complete to the best of psy knowledge and belief.  SIGNATURE OF PRINT NAME NEARBURG PRODUCING COMPANY	Oordinator 2/3/99  TELEPHONE NO.214-739-1778
(This space for State Use)  APPROVED BY TITLE THE PARTY OF THE PARTY O	DATE 3/2/2000
CONDITIONS OF APPROVAL, IF ANY:	