

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

FORM APPROVED
OMB NO. 1004-0135
Expires: November 30, 2000

5. Lease Serial No.

LC-065680

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

Shugart "23" Fed

Com #1

9. API Well No.

30-015-30448

10. Field and Pool, or Exploratory Area

North Lusk (Bone Springs)

11. County or Parish, State

Eddy

NM

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Santa Fe Snyder Corp.

3a. Address

550 W. Texas, Suite 1330, Midland, TX 79701

3b. Phone No. (include area code)

915/686-6612

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

(J), 1650' FSL and 1980' FEL, Sec. 23, T-18S, R-31E

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize

☐ Deepen

☐ Production (Start/Resume)

☐ Water Shut-Off

☐ Alter Casing

☐ Fracture Treat

☐ Reclamation

☐ Well Integrity

☐ Casing Repair

☐ New Construction

☐ Recomplete

☒ Other

☐ Change Plans

☐ Plug and Abandon

☐ Temporarily Abandon

Add Perfs

☐ Convert to Injection

☐ Plug Back

☐ Water Disposal

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

1/26/00 MIRU. Pump 15 bbl hot oil down tbq. GIH W/ 2.25 knife to 8500'. POOH. GIH W/ RBP & ball catcher set # 8505', load hole & test RBP to 1500#. GIH W/ 4" gums perf the Bone Spring @ 2 JSPF from 8254-62; 8286-8300; 8306-10 a total of 55 holes. GIH W/ retrieving tool & Guib Uni V packer. Spot 250 gal 20% HCL. Set packer @ 8139', break down perfs W/ 2800#. Pump 4000 gal 20% gel acid W/ 70 1.3" ball sealers followed W/ 3000 gal gel acid. POOH W/ RBP, ball catcher & packer. GIH W/ 2 7/8" tbq set @ 8330'. GIH W/ pump & rods.

3-11-00 POOH W/ tbq, rods & pump. GIH W/ 5 1/2" 17 & 20# RBP set @ 8510' dump 30' sand on top of RBP. GIH W/ 2 7/8" tbq set @ 8015', rods & pump.

3/22/00 RDMO. Return well to production

Test dated 4/6/00: 81 BO/D; 126 BW/D; 114 MCF

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

Bill Keathly

Title

Regulatory Specialist

Date

7-27-00

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office