-			ARTESIA)		
Form 3160-5 (August 1999)	UNITED STA DEPARTMENT OF TH BUREAU OF LAND MA	IE INTERIOR	153		FORM APPROVED OMB No. 1004-0135 Expires November 30, 2000
SUND	RY NOTICES AND RE	 X			e Serial No. 059569-B
Do not use	this form for proposals	to drill or to recen	iter an A		dian, Allottee or Tribe Name
	well. Use Form 3160-3 (.	[]	- 20m		
	RIPLICATE - Other in	structions on reve	ARTESIA	ິດ 7. If Ur	nit or CA/Agreement, Name and/or
1. Type of Well Oil Well Cas Well		1.5	~о д	S	Name and No.
2. Name of Operator OCEAN ENERGY, IN		IAN) 713-265-		SHUGAI	RT "21" FEDERAL # 2
3a. Address 1001 FANNIN		3b. Phone No. (in		9. API	Well No. 30-015-31013
HOUSTON, TE	XAS 77002	713-265-68		IU. Field	and Pool, or Exploratory Area
4. Location of Well (Foolage, Se 660 FNL & 800	rc., T., R., M., or Survey Descrip FWL SEC. 21 T18	vion) S-R31E EDDY C	CO. NM		RT - MORROW
	wt. D			EDDY	
12. CHECK A	PPROPRIATE BOX(ES)	TO INDICATE NA	TURE OF NOTICE	, REPORT, O	OR OTHER DATA
TYPE OF SUBMISSION					
Notice of Intent		Deepen	_	Start/Resume)	Water Shut-Off
	Alter Casing Casing Repair	Fracture Treat New Construction	n Reclamation		Well Integrity Other
Subsequent Report	Change Plans			Abandon	
Final Abandonment Notice 3. Describe Proposed or Complete If the proposal is to deepen dirt Attach the Bond under which ti following completion of the inn	Change Plans Convert to Injection Convert to Injection d Operation (clearly state all pre- ctionally or recomplete horizor he work will be performed or prolved operations. If the operational folded operations. If the operational Abandonment Notices shall	Plug and Abando Plug Back Plug Back Plug Back Plug Back Plug Back Plug Back Plug Back Plug Back Plug Back	M Temporarily Water Dispose estimated starting date of ations and measured and file with BLM/BIA. Re- paralleling or moments	al of any proposed true vertical de quired subseque	work and approximate duration the pths of all pertinent markers and zo ent reports shall be filed within 30 rval, a Form 3160-4 shall be filed e been completed, and the operator
 Final Abandonment Notice Describe Proposed or Complete If the proposal is to deepen dire Attach the Bond under which the following completion of the inst testing has been completed. Fi determined that the site is ready Ocean Energy, FEDERAL # 2 from 660' FNL & 800 The reason for 	Change Plans Convert to Injection Convert to Injection d Operation (clearly state all pe- ctionally or recomplete horizor he work will be performed or prolved operations. If the operational Abandonment Notices shal for final inspection.)	Plug and Abando Plug Back Plug Back Plug Back Plug Back reminent details, including itally, give subsurface loc provide the Bond No. on f ion results in a multiple c l be filed only after all re approval to m 750' FWL of Se 21 T18S-R31E E that this loca	m Temporarily Water Dispose estimated starting date of ations and measured and file with BLM/BIA. Re completion or recompleting uirements, including r source the locat action 21 T185 addy Co. NM.	ion of th -R31E Edc	peths of all pertinent markers and zc int reports shall be filed within 30 irval, a Form 3160-4 shall be filed of a been completed, and the operator heir SHUGART "21" hy Co. NM to Geological position H
 Final Abandonment Notice Describe Proposed or Complete If the proposal is to deepen dire Attach the Bond under which ti following completion of the inst testing has been completed. Fi determined that the site is ready Ocean Energy, FEDERAL # 2 fro 660' FNL & 800 The reason for and recover a § 	Change Plans Convert to Injection convert to Injection doperation (clearly state all pe- ectionally or recomplete horizor he work will be performed or proved operations. If the operational Abandonment Notices shal for final inspection.) Inc. requests the Dm 1650' FNL & 1 ' FWL of Section this request is greater amount of	Plug and Abando Plug Back Plug Back Plug Back Plug Back reminent details, including itally, give subsurface loc provide the Bond No. on f ion results in a multiple c l be filed only after all re approval to m 750' FWL of Se 21 T18S-R31E E that this loca	m Temporarily Water Dispose estimated starting date of ations and measured and file with BLM/BIA. Re completion or recompleting uirements, including r source the locat action 21 T185 addy Co. NM.	ion of th -R31E Edc	peths of all pertinent markers and zc int reports shall be filed within 30 irval, a Form 3160-4 shall be filed to been completed, and the operator meir SHUGART "21" Hy Co. NM to Geological position Geological position
 Final Abandonment Notice Describe Proposed or Complete If the proposal is to deepen dire Attach the Bond under which to following completion of the inst testing has been completed. Fi determined that the site is ready Ocean Energy, FEDERAL # 2 fro 660' FNL & 800 The reason for and recover a g I hereby certify that the foregoin Name (Prinued/Typed) 	Change Plans Convert to Injection convert to Injection doperation (clearly state all pe- ectionally or recomplete horizor he work will be performed or proved operations. If the operational Abandonment Notices shal for final inspection.) Inc. requests the Dm 1650' FNL & 1 ' FWL of Section this request is greater amount of	Plug and Abando Plug Back Plug Plug Back Plug Plug Back Plug Plug Back Plug Plug Back Plug Plug Plug Plug Plug Plug Plug Plug Plug Plug Plug Plug Plug Plug Plug	M Temporarily Water Dispose estimated starting date of ations and measured and file with BLM/BIA. Re completion or recompleti- equirements, including r dove the locat action 21 T185 addy Co. NM.	ion of th -R31E Edc	peths of all pertinent markers and zc int reports shall be filed within 30 irval, a Form 3160-4 shall be filed to been completed, and the operator meir SHUGART "21" Hy Co. NM to Geological position Geological position
 Final Abandonment Notice Describe Proposed or Complete If the proposal is to deepen dire Attach the Bond under which the following completion of the inst testing has been completed. Fi determined that the site is ready Ocean Energy, FEDERAL # 2 from 660' FNL & 800 The reason for and recover a st 	Change Plans Convert to Injection convert to Injection doperation (clearly state all pe- ectionally or recomplete horizor he work will be performed or proved operations. If the operational Abandonment Notices shal for final inspection.) Inc. requests the Dm 1650' FNL & 1 ' FWL of Section this request is greater amount of	Plug and Abando Plug Back Plug Back Plug Back Plug Back reminent details, including itally, give subsurface loc provide the Bond No. on f ion results in a multiple c l be filed only after all re approval to m 750' FWL of Se 21 T18S-R31E E that this loca	m Temporarily Water Dispose estimated starting date of ations and measured and file with BLM/BIA. Re completion or recompleting uirements, including r source the locat action 21 T185 addy Co. NM.	ion of th -R31E Edc	peths of all pertinent markers and zc int reports shall be filed within 30 irval, a Form 3160-4 shall be filed of a been completed, and the operator heir SHUGART "21" hy Co. NM to Geological position REAL POINT
 Final Abandonment Notice Describe Proposed or Complete If the proposal is to deepen dire Attach the Bond under which to following completion of the inst testing has been completed. Fi determined that the site is ready Ocean Energy, FEDERAL # 2 fro 660' FNL & 800 The reason for and recover a g I hereby certify that the foregoin Name (Prinued/Typed) 	Change Plans Convert to Injection convert to Injection doperation (clearly state all pe- ectionally or recomplete horizor he work will be performed or proved operations. If the operational Abandonment Notices shal for final inspection.) Inc. requests the Dm 1650' FNL & 1 ' FWL of Section this request is greater amount of	Plug and Abando Plug Back Plug Plug Back Plug Plug Back Plug Plug Back Plug Plug Back Plug Plug Plug Plug Plug Plug Plug Plug Plug Plug Plug Plug Plug Plug Plug	M Temporarily Water Dispose estimated starting date of ations and measured and file with BLM/BIA. Re completion or recompleti- equirements, including r dove the locat action 21 T185 addy Co. NM.	ion of th -R31E Edc	peths of all pertinent markers and zc int reports shall be filed within 30 irval, a Form 3160-4 shall be filed to been completed, and the operator meir SHUGART "21" Hy Co. NM to Geological position Geological position
 Final Abandonment Notice Describe Proposed or Complete If the proposal is to deepen dire Attach the Bond under which the following completion of the insteady Ocean Energy, FEDERAL # 2 from 660' FNL & 800 The reason for and recover a standard st	Change Plans Convert to Injection ed Operation (clearly state all per- cetionally or recomplete horizor he work will be performed or prolved operations. If the operational Abandonment Notices shal for final inspection.) Inc. requests the DM 1650' FNL & 1 ' FWL of Section this request is greater amount of g is true and correct	Plug and Abando Plug Back Plug Plug Back Plug Plug Back Plug Plug Back Plug Plug Back Plug Plug Plug Plug Plug Plug Plug Plug Plug Plug Plug Plug Plug Plug Plug	M Temporarily Water Dispose estimated starting date of ations and measured and file with BLM/BIA. Re- completion or recompleti- equirements, including r dove the locat action 21 T185 addy Co. NM. ation will enh- erves.	al of any proposed it true vertical de quired subseque on in a new inte eclamation, have ion of th -R31E Edd ance the	peths of all pertinent markers and zc int reports shall be filed within 30 irval, a Form 3160-4 shall be filed to been completed, and the operator meir SHUGART "21" Hy Co. NM to Geological position Geological position
 Final Abandonment Notice Describe Proposed or Complete If the proposal is to deepen dire Attach the Bond under which to following completion of the insteady Ocean Energy, FEDERAL # 2 fro 660' FNL & 800 The reason for and recover a generative signature 	Change Plans Convert to Injection ed Operation (clearly state all per- cetionally or recomplete horizor he work will be performed or prolved operations. If the operational Abandonment Notices shal for final inspection.) Inc. requests the DM 1650' FNL & 1 ' FWL of Section this request is greater amount of g is true and correct	Plug and Abando Plug Back Plug Back	M Temporarily Water Dispose estimated starting date of ations and measured and file with BLM/BIA. Re- completion or recompletion equirements, including r dove the locat action 21 T185 addy Co. NM. ation will enh- erves. Agent 11/18/00 STATE OFFICE US	al of any proposed I true vertical de quired subseque on in a new inte eclamation, have ion of th -R31E Edd ance the ance the SE	peths of all pertinent markers and zc int reports shall be filed within 30 irval, a Form 3160-4 shall be filed to been completed, and the operator meir SHUGART "21" Hy Co. NM to Geological position Geological position

DISTRICT I 1625 M. Franch Dr., Mobbs, NM 56240 DISTRICT II

•

811 South First, Artesis, NM 88210

DISTRICT III 1000 Rio Brazos Rd., Artec, NM 87410

DISTRICT IV 2040 South Pacheco, Santa Fe, KH 87505 State of New Mexico

Energy, Minerals and Natural Resources Department

Form C-102 Revised March 17, 1999

Submit to Appropriate District Office State Lease - 4 Copies Fee Lease - 3 Copies

OIL CONSERVATION DIVISION

2040 South Pacheco Santa Fe, New Mexico 87504-2088

AMENDED REPORT

WELL LOCATION AND ACREAGE DEDICATION PLAT

API Number		Pool Code		<u> </u>	Pool Name								
			00		SHUGART-MORROW								
Property Code			Property Name SHUGART FEDERAL "21"				Well Number						
25474				2									
OGRID No.		Operator Name OCEAN ENERGY				Elevation							
169355													
Surface Location													
UL or lot No. Section	Township						Feet from the Bast/West line						
D 21	18 S	31 E		660	NORTH	-800	WEST	EDDY					
Bottom Hole Location If Different From Surface													
	TOWNSHIP	there a		Leet How The	North/South ime	Feet from the	Kast/west inte	County					
Dedicated Acres Joint		1											
	or Infill Ca	nsolidation	Code Or	der No.									
320													
NO ALLOWABLE	WILL BE A	SSIGNED	TO THIS	COMPLETION	UNTIL ALL INTER	RESTS HAVE BE	EN CONSOLID	ATED					
<u> </u>	OR A I	NON-STAN	IDARD UN	IT HAS BEE	N APPROVED BY	THE DIVISION							
			1	T									
]			ļ		OPERATO	R CERTIFICAT	TION					
3641 <u>.8' ⁶⁰ 3</u> 641.6']			1			, certify the the in						
800'0	LAT - N32	44'18.3"	!	1		best of the show	i is true and compl ledge and belief.	ete to the					
	LONG - WI	03*52'49.7'	1	1									
3635.8' 3639.8'	1						$-(\cdot $						
	1			Ĺ		100	1 Jan	u					
├ ─────	+					Signature							
	1				<i>*</i> :	Jue T.							
Ē	Ì		Į	OCD - ARTE	14 1	Printed Name							
	Ì	1		OCD - AR	:D	Agent		[
	l	1		ع (م) (من المراجع) ا	STA	11/18/	/00						
				i		Date							
						SURVEYO	R CERTIFICAT	ION					
	I		Į	1		I hereby certify	that the well locat	ion shown					
			1	i		on this plat wa	e plotted from fleid	t notes of					
				1		Supervison and	made by me er i that the same is	true and					
		1	1	1		correct to the	best of my bells	r.					
				1									
				1	-1 (, 2								
]	L	- JURCE		Signature	Leve Mer						
			₹	HO MOWE		Professional	our or						
				ק אור	NZ NON NON		797	_ <u> </u> _					
				75 .2 0			AT	[<u>[</u>]					
			3		NECEN								
			ļ	ED .	1/1-		you used	<u>// </u>]					
			1	-		Certificate No	Gorys Ch. Jones	7977					
				BASIN SUBVEYS									
				JONNER HID WEWE S: 35 ED	NECEIN	I hereby certify on this plat was artual surveys supervison and correct to the Octo Date Survey Signature & Professional Certificate NC	s platted from flaid made by me er i that the same is best of my beke a Grand Review a Grand Rev	Ion shown I nates of under my I'rw and					

