



- △ Wind Direction Indicators
(wind sock or streamers)
- △ H2S Monitors
(alarms at bell nipple and shale shaker)
- Briefing Areas
- Remote BOP Closing Unit
- Sign and Condition Flags

EXHIBIT "D"
RIG LAY OUT PLAT

KUKUI OPERATING COMPANY
HIGHLANDS "14" FEDERAL # 1
UNIT "F" SECTION 14
T19S-R21E EDDY CO. NM