| Form 3160-5 November 1983) Formerly 9-331) BUREAU OF LAND MANAGE | SUBMIT IN TRIPLICATE (Other instructions of reverse side) MENT | Expires August 31, 1985 5. LEASE DESIGNATION AND SERIAL NO. LC-063567 6. IF INDIAN, ALLOTTEE OR TRIBE NAME | | |
|---|--|---|--|--|
| SUNDRY NOTICES AND REPOR (Do not use this form for proposals to drill or to deepen or Use "APPLICATION FOR PERMIT_" for | plug back to a different reservoir. uch proposals.) | O. IF INDIAN, ALLOTTEE OF TRIBE NAME | | |
| I. OIL CAS OTHER WIW | JUN 08 1984 | 7. UNIT AGREEMENT NAME | | |
| 2 NAME OF OPERATOR | 0. C. D. | 8. PARM OR LEASE NAME | | |
| | ARTESIA, OFFICE | Yates Federal | | |
| Yates Energy Corporation | Anteon | 9. WBLL NO. | | |
| Sunwest Centre, Suite 919, Roswell, Ne. 4. Location of WELL (Report location clearly and in accordance with | | 12 10. FIELD AND POOL, OR WILDCAT | | |
| 4. Location of well (Report location clearly and in accordance who See also space 17 below.) At surface 330' FNL & 1650' FEL | | McMillan 7-Rivers Oues 11. SBC, T., E., M., OR BLK. APD SURVEY OR AREA Sec 7, T-20S, R-27E | | |
| PERMIT N 15 ELEVATIONS (Show whether DF, RT, GR, etc.) | | 12. COUNTY OR PARISH 13. STATE | | |
| <u>3367' G</u> | Eddy N.M. | | | |
| 16 Check Appropriate Box To Indic | ate Nature of Notice, Report, or | Other Data | | |
| NOTICE OF INTENTION TO : | BUBAL | BUBSEQUENT REPORT OF : | | |
| TEST WATER SHUT-OFF PULL OR ALTER CASING | WATER SHUT-052 | EEFAIRING WELL | | |
| PRACTURE THEAT MULTIPLE COMPLETE | FRACTURE TREATMENT | ALTERING CASING | | |
| PRACTOR CLEAT MULTIPLE COMPLETE SHOOT OR AUDIZE ABANDON* X REPAIR WE CHANGE FLANS X | SHOOTING OR ACIDIZING | ABANDON MENT* | | |
| REPAIR WE CHANGE PLANE X | (Other: | a of multiple completion on We. | | |

Other) (Other) NOTE: Report results of multiple completion on Well Completion or Recompletion Beport and Log form (DESCRIPTIONSED OF COMPLETED OFFRATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markets and gones yet, nent to this work.)

6/5/84 Per our telephone conversation of this date, attached for your use as an aid to your understanding of our present predicament is a diagrammatic sketch of the injection set up and downhole tubular and packer originally submitted and followed in the original installation in 1970. This schematic may or may not be in your well file. Please disregard the steam injection line as this was not installed.

As per telephone conversation, June 4th, to state that we had a small pulling unit available to work on this well, on June 4th we entered the well and learned that the 2 3/8" tbg had rusted, corroded and parted. Present plugging material in the csg is at 24' from surface. It appears to be scale, rust and debris. This well is no longer useful to us as an injector or a producer. We wish to abandon it.

In order to attempt to satisfy the requirements to adequately plug this well, we plan to move in a pulling unit and circulating-rotating equipment to "fish," mill and otherwise clean out the hole to prepare for abandonment by cementing same.

We request approval to place a 100' cement plug 50' below and above the 7' casing shoe at 435' (plug 485' to 385') and to install a regulation marker with 10 sxs of cmt at the surface.

| ī. | I hereby certify that the foregoing is true and correct SINED | TITLE John R. McMinn, Engineer | DATE | June 5, | 1984 |
|----|--|--------------------------------|------|---------|------|
| | (This space for Federal or State office use) APPROVED BY CONJATIONS OF APPROVAL, IF ANY. | TITLE | DATE | | |

*See Instructions on Reverse Side

