	VITLE Supervisor District II	DATE #191 0 1 1304
	Leslie A. Clements	MAY 3 1 1984
16969	Original Signed By	
The following	Reservoir Engineer	May 30, 1984
is. I hereby certify that the information shove is true and complet	te to the best of my knowledge and belief.	
.)		THE STATE OF THE S
	•	
•		
		•
See procedure attached.		
WORK) SEE NOCE 11941		
7. Describe Proposed or Completed Operations (Clearly state all work) SEE RULE 1103.	pertinent uctures, una give periinem darra, me-	
7. Describe Proposed or Completed Operations (Clearly state all	nertinent details, and give pertinent dates, incl	uding estimated date of starting any proposed
Plug back & Test Delaware		
	OTHER	
FULL DE ALTER CASING		
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	AEGA MAN MANAGAMENT
PERPORM REMEDIAL WORK	BANDON REMEDIAL WORK	BEUG AND ABANDONMENT
		ALTERING CASING
NOTICE OF INTENTION TO:	SUBSEC	The Control of the Control of Con
	indicate Nature of Notice, Report of	ENT REPORT OF:
		Other Data
3254' GI		Eddy (((()))
THE IS. Elevation (S.	how whether DF, RT, GR, etc.)	12. County
		- A Jack Sand Sand Sand Sand Sand Sand Sand Sand
THE East LINE, SECTION 15 TOWNSHI	21S HANGE 27E N	
UNIT LETTER I 1980 PEET FROM THE S	South LINE AND 660 PRET	101200 Oh. LEIII
Leagues of Well		lo: II. Danie
P. O. Box 1933, Roswell, New Mexico	88201	10. Field and Pool, or Wildcat
	00001	9. Neil 190.
Harvey E. Yates Company		9. Well No.
Name of Operator		
OIL GAS OTHER-		8. Farm or Lease liame
		Cedar Hills Unit
IDO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPE USE "APPLICATION FOR PERMIT -" (FORM C-1	N OR PLUG BACK TO A DIFFERENT NESERVOIS.	7. Unit Agreement Name
SUNDRY NOTICES AND REPORTED TO THE SET OF TH	ORTS ON WELLS	
and the same of th		0G-5809
OPERATOR /	ARTESIA, OFFICE	
U.S.O.S.	O, C. D.	5, State Oil & Gas Lease No.
one K	1	State X Fee
SANTA F	FE, NEW MEMAYO38 1 5 1984	5a. Indicate Type of Lease
	P. O. BCX 2088	Revised 10-1-78
	SERVATIONE CENTEDIBY	Form C-103
INERGY AND MINERALS DEPARTMENT	The same of the sa	
STATE OF NEW MEXICO		

\* AC NOTED DN 2nd Page & MUD BETWEEN ALL DOUBLE