

N. M. O. C. C. COPY
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LAS CRUCES 028240-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

H. C. Rawson "A"

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

Catty

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Section 13, T 20 S, R 29 E

12. COUNTY OR PARISH

Edgy

13. STATE

New Mexico

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Skelly Oil Company

3. ADDRESS OF OPERATOR

Box 730 - Hobbs, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

**660' FSL & 1540' FSL
Section 13, T 20 S, R 29 E**

14. PERMIT NO.

H. C. Rawson

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3331 GR

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

SUBSEQUENT REPORT OF:

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Well plugged & abandoned in the following manner:

1. Moved in and rigged up casing pullers, pulled rods and tubing.
 2. Pulled 96 jts (1370') of 8-1/4" casing.
 3. Spotted cement plug from 1397' to 1122' with 135 sacks of cement.
 4. Shot off 10-3/4" OD casing at 971'; could not pull.
 5. Spotted 94 sack cement plug from 1122' to 985' (cement inside 10-3/4" OD casing.)
 6. Squeezed through hole at 970' in 10-3/4" OD casing, Displacing 18 sacks of cement into formation behind casing, leaving 82 sacks in casing from 1040' to 993'.
 7. Ran Free Point Indicator.
 8. Spotted 125 sack cement plug from 993' to 772'.
 9. Perforated 10-3/4" OD casing at 750' with 3 holes.
 10. Squeezed through hole in 10-3/4" OD casing at 535' and perfs. 750' with 400 sacks of cement. Found top of cement at 712'.
 11. Cut and pulled 10-3/4" OD casing from 444'.
 12. Spotted 400-sack cement plug from 712' to 60'.
 13. Spotted 60-sack cement plug from 60' to surface and installed 4" steel marker.
 14. Well plugged and cemented from total depth of 1397' to surface.
- Date work performed: March 7, 1966, to March 26, 1966.**

18. I hereby certify that the foregoing is true and correct

SIGNED

**(ORIGINAL)
H. E. Ast**

TITLE **District Superintendent**

DATE **March 30, 1966**

(This space for Federal or State office use)

APPROVED BY **1966**
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

APPROVED
OCT 2 1966
R. L. BEEKMAN
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

RECEIVED
APR 1 1966
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

(RECEIVED 1 JAN 1964)