

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN ^{5 Copies} ~~ONE~~ ^{ICATB*} ~~ICATB*~~
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL ☒ WELL GAS ☐ WELL OTHER ☐		5. LEASE DESIGNATION AND SERIAL NO. L.C. 029096 (A)	
2. NAME OF OPERATOR Harris G. Eastham, Jr.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME <i>Copy to B.</i>	
3. ADDRESS OF OPERATOR % K. Yarbrough, Box 1471, Midland, Texas		7. UNIT AGREEMENT NAME J	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' from the south line and 1980' from the East line of Sec. 20, T20S, R30E.		8. FARM OR LEASE NAME Colglazier	
14. PERMIT NO.		9. WELL NO. 1	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3247		10. FIELD AND POOL, OR WILDCAT Barber	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 20 - 20S - 30E	
		12. COUNTY OR PARISH Eddy	
		13. STATE New Mexico	

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☒

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

T.D. 1600'

7" - 1502' - (65 sx + Mud)

8-5/8" - 448' - (50 sx + Mud)

RECEIVED

AUG 8 1967

D. C. C.
ARTESIA, OFFICE

Propose to permanently abandon well as follows:

1. Spot cement plug from T.D. to 1400'
2. Cut and pull 7" csg. @ 550' or lower
3. Spot solid cement plug from 1250' to 350' (cement to be salt saturated)
4. Cut and pull as much 8-5/8" csg. as pract.
5. Spot 100' cement plug in and out 8-5/8" stub
6. Spot 20' cement plug at surface
7. Heavy mud to be placed between cement plugs
8. Install regulation marker

Above work is in conformance with oil - potash regulations

CC: Paul Corbin, PCA, Box 31, Carlsbad, New Mexico 88220

RECEIVED
AUG-7-1967
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE **Agent**

DATE **August 4, 1967**

(This space for Federal or State office use)

APPROVED

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED
AUG - 7
R. L. BECKMAN
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

NOTIFY DEPT. OF REVENUE
WITHIN 30 DAYS
all plugs

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed-off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.