

NO. OF COPIES RECEIVED	4
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	2

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

AUG 3 1970

O. C. C.

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
E-997

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS</p> <p align="center"><small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small></p>		<p align="center">ARTESIA, OFFICE</p>	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name		
2. Name of Operator	8. Farm or Lease Name		
WILLIAM A. & EDWARD R. HUDSON	Eddy "BD" State		
3. Address of Operator	9. Well No.		
Box #198, Artesia, New Mexico 88210	1		
4. Location of Well	10. Field and Pool, or Wildcat		
UNIT LETTER A , 660 FEET FROM THE North LINE AND 330 FEET FROM	Dos Hermanos, Y-SR		
THE East LINE, SECTION 32 TOWNSHIP 20S RANGE 30E NMPM.			
15. Elevation (Show whether DF, RT, GR, etc.)	12. County		
3359 Gr.	Eddy		

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

On July 28, 1970, this well was plugged and abandoned as follows:

Pumped 212 sacks of neat Class "C" cement (volume of casing and hole)
plus an additional 28 sacks to fill hole. Cement was mixed with water containing
potash salts. A 4" pipe marker was placed at surface.

5 1/2" pipe - Top cement at 100'

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u><i>Ralph L Gray</i></u>	TITLE <u>Consulting Engineer.</u>	DATE <u>July 30, 1970</u>
APPROVED BY <u><i>B. L. Hammett</i></u>	TITLE <u>OIL AND GAS INSPECTOR</u>	DATE <u>DEC 14 1970</u>

CONDITIONS OF APPROVAL, IF ANY: