

Form 9-581a
(Feb. 1951)

(SUBMIT IN TRIPLICATE)

Land Office N. M.Lease No. C 3365

Unit _____

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

JUL 20 1962

SUNDRY NOTICES AND REPORTS ON WELLS

ARTESIAN OFFICE

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 21, 1962

Well No. 42-29 is located 1900 ft. from N line and 500 ft. from E line of sec. 2929 NE

(1/4 Sec. and Sec. No.)

20

(Twp.)

26

(Range)

(Meridian)

Eddy

(County or Subdivision)

New Mexico

(State or Territory)

(Field)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

WORK BEGAN 5-10-62

WORK COMPLETED 5-17-62

1. Total depth of well 3000'. 8 1/2" 1926-Mud. 7" 2562-40 SX
2. Plugged back total depth 2457'.
3. Spotted a 40 sack cement plug at 2562'.
4. Mudded hole with high quality gel mud.
5. Shot 7" casing at 2535, 2900, 2100, 1905, 1920, 1840, 1760, 1705.
6. Recovered 1715' of 7" casing
7. 8-5/8" casing was run to 1930' and mudded in
8. Shot 8-5/8" casing at 1700', 1600', 1545', 1450'.
9. Recovered 1454' of casing.
10. Spotted cement as follows: 25 sz 2675-2475, 15 sz 1975-2035, 60 sz 1665-1800, 25 sz 1415-1462, 40 sz 824-874, 40 sz 101-151, 10 sz Top.
11. Erected a 4" marker.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Wilshire Oil CompanyAddress 300 Fillmore StreetDenver 6, ColoradoBy Stanley Bairin
Title Superintendent

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

40

41

42

43

44

45

46

47

48

49

50

51

52

53

54

55

56

57

58

59

60

61

62

63

64

65

66

67

68

69

70

71

72

73

74

75

76

77

78

79

80

81

82

83

84

85

86

87

88

89

90

91

92

93

94

95

96

97

98

99

100