

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN 1 APPLICATION*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-039365

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Sig Eddy Unit

8. FARM OR LEASE NAME

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Horton-Draw-Strawn (Oil)

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

19-21-28 N4M4

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Pan American Petroleum Corporation ✓

3. ADDRESS OF OPERATOR

Box 68 - Hobbs, New Mexico 38240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)

At surface

660' FSL X 660' FEL, Sec. 19, (SE/4 SE/4, Unit P)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3198' EDB

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETION ☐ABANDON* ☒CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

This well has been depleted. No other completion possibilities exist. Pursuant to
telephone approval of 2-19-64 between Messrs. J. A. Knauf and J. W. Meek. It is now
proposed to plug and abandon as follows:

1. Spot 40 ex plug from 10,600' to 10,750'.
2. Cut & pull 7-5/8" casing from approx. 9300' and spot 50 ex plug in and out of stub.
3. Spot additional plugs; 50 ex - 8000' to 7900'; 50 ex - 6200' to 6100'; 50 ex - 4600' to 4500'; 100 ex in and out of 9-5/8" casing stub at 3252'
4. Set CI bridge plug at 1700' and cap with 50' cement.
5. Spot 5 ex plug at surface and erect PIA marker. (All intervals to be filled with heavy mud laden fluid)
6. Location to be cleaned and restored to its natural contour.

Casing Record

13-3/8" CSA 478' with 550 ex circ.

9-5/8" CSA 1450' " 1450 ex circ.

7-5/8" CSA 1189' " 500 ex top cement at approx. 9300'

TD - 12,457

PBD - 10,900

18. I hereby certify that the foregoing is true and correct

SIGNED

S. A. STANLEY

TITLE Area Superintendent

DATE 2-20-64

(This space for Federal or State office use)

APPROVED BY
CONDITION OF APPROVAL, IF ANY:

TITLE

DATE

RECEIVED
FEB 27 1964
F. E. D.
DISTRICT OFFICE

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

23-09-11
1963
U.S. GOVERNMENT PRINTING OFFICE