		P		<u>_</u>			on	dent	al		
CISTRI SANTA FT FILE U.3 G.5. LAND OF FICE TRANSPORTER			MISC		NEOU	S REP	ORTS	COMMIS	LS		FORM C-10 (Rev 3-55)
Name of Company			ubmit to ap	propriate			as per C	ommission	Rule 1	106)	
Lease	Kobert	G. Hanagan			Addres	Box		Roswell,	New	Mexi	co
Date Work Perform	Tepes S		Well No 1	. Unit	Letter D	Section 32	Townshi	P 21 S	R	апде	24 E
4/28/	54 <u> </u>		vildcat			1	County	Eddy			
Beginning Dr	illing Operati	TH	IS IS A REP								
Plugging	ining Operati] Casing Te:] Remedial V		ient Job	G	Cther	(Explain):			
								ſ	e r	• < ;	VED
Vitnessed by M	. L. Arms	trong	Positi Su	en I pervis c)r	Cc	ompany 01		6 1 1 1 1 1 1 1 1 1 1	4 	196 4 National States
Vitnessed by M	. L. Arns		SELOW FOR	pervis R REMED	IAL WO	RKREP	01	1 Conser	6 1 1 1 1 1 1 1 1 1 1	4 	1964
M	L. Arms T D		SELOW FOR	perviso	IAL WO	RK REP	OI ORTS O	1 Conser	vatio	n Cor	196 4 National States
DF Elev.			SELOW FOR	REMED IGINAL W	IAL WO Ell Da	RK REP	O1 PORTS O Producing	1 Conser NLY 3 Interval	vatio	n Cor	1964 mission
D F Elev. Tubing Diameter	T D	FILL IN E	SELOW FOR	REMED IGINAL W	IAL WO Ell Da		O1 PORTS O Producing	1 Conser NLY 3 Interval	vatio	n Cor	1964 mission
D F Elev. Subing Diameter Perforated Interval(s	T D	FILL IN E	SELOW FOR	REMED Iginal W TD	IAL WO ELL DA		O1 PORTS 0 Producing	1 Conser NLY 3 Interval	vatio	n Cor	1964 mission
D F Elev. Subing Diameter Perforated Interval(s	T D	FILL IN E	BELOW FOR	REMED Iginal W TD	IAL WO ELL DA	PRK REP TA	O1 PORTS 0 Producing	1 Conser NLY 3 Interval	vatio	n Cor	1964 mission
M D F Elev. Tubing Diameter Perforated Interval(s pen Hole Interval Test	T D	FILL IN E	BELOW FOR OR PB RESU	REMED IGINAL W TD 0	IAL WO ELL DA il String roducing	PRK REP TA Diameter Formatic	01 PORTS () Producing m(s)	1 Conser NLY 3 Interval Oil S GO	vatio	n Con Comple	1964 mission tion Date
M D F Elev. Subing Diameter Perforated Interval(s Open Hole Interval Test Before	T D s) Date of	FILL IN E	BELOW FOR OR PB RESU	REMED IGINAL W TD 0 LTS OF s Productio	IAL WO ELL DA il String roducing	PRK REP TA	01 PORTS () Producing m(s)	1 Conser NLY g Interval Oil S	vatio	n Con Comple	1964 mission tion Date
M D F Elev. Tubing Diameter Perforated Interval(s pen Hole Interval Test Before Workover After	T D s) Date of	FILL IN E	BELOW FOR OR PB RESU	REMED IGINAL W TD 0 LTS OF s Productio	IAL WO ELL DA il String roducing	PRK REP TA Diameter Formatic	01 PORTS () Producing m(s)	1 Conser NLY 3 Interval Oil S GO	vatio	n Con Comple	1964 mission tion Date
M D F Elev. Fubing Diameter Perforated Interval Perforated Interval Pen Hole Interval Test Before Workover After Workover	T D s) Date of Test	FILL IN E	Subsection Statements	REMED IGINAL W TD O LTS OF s Production MCFPD	IAL WO ELL DA il String roducing WORKO on V	PRK REP TA	01 Producing producing duction D	1 Conser NLY GINTERVAL OILS OILS GO Cubic fee	tring De R tr/Bbl	n Con Comple pth	1964 mission tion Date
M D F Elev. Fubing Diameter Perforated Interval Perforated Interval Open Hole Interval Test Before Workover After Workover OIL pproved by	T D s) Date of Test	FILL IN E	Subsection Statements	REMED IGINAL W TD 0 LTS OF s Production MCFPD	IAL WO ELL DA il String roducing WORKO on V I hereby to the bo	PRK REP TA	01 Producing producing on(s) duction D	1 Conser NLY 3 Interval Oil S GO Cubic fee formation give.	tring De R tr/Bbl	n Con Comple pth	Well Potential MCFPD
D F Elev. Fubing Diameter Perforated Interval(s Open Hole Interval Test Before Workover After Workover OIL pproved by	T D s) Date of Test	FILL IN E	Subsection Statements	REMED IGINAL W TD 0 LTS OF s Production MCFPD	IAL WO ELL DA il String roducing WORKO on V I hereby to the bu	PRK REP TA	01 Producing producing producing pon(s) duction D hat the in knowledg	1 Conser NLY 3 Interval Oil S GO Cubic fee formation give.	tring De R tr/Bbl	n Con Comple pth	Well Potential MCFPD