

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	3

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

NOV 6 1967

ARTESIA, OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Harvey E. Yates	8. Farm or Lease Name Honda-Singer "A"
3. Address of Operator Yates Bldg. Artesia, N.M.	9. Well No. 1
4. Location of Well UNIT LETTER P 660 FEET FROM THE South LINE AND 660 FEET FROM THE East LINE, SECTION 7 TOWNSHIP 20S RANGE 27E NMPM.	10. Field and Pool, or Wildcat McMillan-Morrow Gas
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Eddy

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER Plug back & treated w/nitro glycerin <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

T.D. 10973
Plugged back to 10,408 w/ 5/8" pea gravel.
Shot 80' w/200 qts. nitro glycerin.
Top of shot @ 10,328 w/ 2 time bombs. Tamped w/35' pf pea gravel.
Set 5 1/2" 17# bridge plug @ 10,291. Gmt w/50 cks. Top of cnt 10,171.
Shot to go off @ 1:40 PM 9-24-64.
9-25-64 Cleaned out to T.D. 10,408. Ran M Otis packer. Set @ 10,086.
Placed back on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED **W. A. Gressitt** TITLE **Bookkeeper** DATE **Oct. 30, 1967**

APPROVED BY **W. A. Gressitt** TITLE **OIL AND GAS INSPECTOR** DATE **JUN 13 1968**

CONDITIONS OF APPROVAL, IF ANY: