2 101000 4 1500	ALULIE & * AAT		·	
NO. OF COPIES RECEIVED				
DISTRIBUTION	NEWI	MEXICO OIL CO	NSERVATION COMMISSION	Form C-104
SANTA FE	,,,,		OR ALLOWABLE	Supersedes Old C-104 and C-
FILE //-		KEQOEO1 1	AND	Effective 1-1-65
	ALITHODIZA-	TION TO TOA	NSPORT OIL AND NATURA	I GAS
U.S.G.S.	AUTHURIZA	HON TO TRAI	13FORT OIL AND NATORA	AL GAS
LAND OFFICE	1			
TRANSPORTER OIL				RECEIVED
GAS /				BEDFIA
OPERATOR /				
PRORATION OFFICE				(A) A) A 3 1965
Redfern Developme	at Corp.			UUN 2 3 1965
Addresss				Ö. C. C.
Box 1747, Midland			Other (Please explain)	ARTEBIA, DEFICE
Reason(s) for filing (Check proper box)			Office (1 sease explain)	•
New Well	Change in Transp			
Recompletion	Oil	Dry Gas	·	
Change in Ownership	Casinghead Gas	Conden	sate	
DESCRIPTION OF WELL AND Lease Name	LEASE V		ne, Including Formation	Kind of Lease State, Federal or Fee Forture
Winston		India:	n Rasin Mor row	State, Federal or Fee Federal
Location				
Unit Letter K ; 208	Feet From The_	South Lin	e and 1980 Feet F	rom The Wast
o				
Line of Section 31 , Tov	wnship 215	Range 2	AE , NMPM,	Eddy Count
Name of Authorized Transporter of Oil Name of Authorized Transporter of Oil		ate 🔀	Address (Give daaress to which to	approved copy of this form is to be sent) n Club Bldg., Abilene, Tex
Name of Authorized Transporter of Car Southern Union Ga	singhead Gas or Unit Sec.	Dry Gas K	Address (Give address to which address (Give address to which a Box 199, Artesia, I is gas actually connected?	n Club Bldg., Abilene, Tempapproved copy of this form is to be sent)
Name of Authorized Transporter of Car Southern Union Go If well produces oil or liquids, give location of tanks.	singhead Gas or as Co. Unit Sec.	Dry Gas Twp. Rge.	Address (Give address to which to Address (Give address to which to Box 199, Artosia, Is gas actually connected?	a Club Bldg., Abilene, Tempapproved copy of this form is to be sent) New Mexico 88210 When
Name of Authorized Transporter of Car Southern Union Go If well produces oil or liquids, give location of tanks. If this production is commingled wi COMPLETION DATA	singhead Gas or as Coo Unit Sec. 1. 31 th that from any othe	Dry Gas Twp. Rge. 215 245 Per lease or pool,	Address (Give address to which to Address (Give address to which to Rox 199, Artosia, Is gas actually connected? No give commingling order number New Well Workover Deeper	n Club Bldg., Abilene, Tem approved copy of this form is to be sent) New Mexico 88210 When
Name of Authorized Transporter of Car Southern Union Ga If well produces oil or liquids, give location of tanks. If this production is commingled wi	singhead Gas or as Coo Unit Sec. 1. 31 th that from any othe	Dry Gas Twp. Rge. 215 245 Per lease or pool,	Address (Give address to which a Address (Give address to which a Rox 199, Artosia, Is gas actually connected? No give commingling order number	approved copy of this form is to be sent) New Mexico 88210 When Plug Back Same Res'v. Diff. Res
Name of Authorized Transporter of Car Southern Union Go If well produces oil or liquids, give location of tanks. If this production is commingled wi COMPLETION DATA Designate Type of Completic	singhead Gas or as Coo Unit Sec. 1. 31 th that from any othe	Dry Gas X Twp. Rge. 215 24E er lease or pool, Gas Well	Address (Give address to which to Address (Give address to which to Rox 199, Artosia, Is gas actually connected? No give commingling order number New Well Workover Deeper	n Club Bldg., Abilene, Temapproved copy of this form is to be sent) New Mexico 88210 When
Name of Authorized Transporter of Car Southern Union Go If well produces oil or liquids, give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded	or Condense or Con	Dry Gas The Right	Address (Give address to which Address (Give address to which Box 199, Artesia, Is gas actually connected? No give commingling order number New Well Workover Deepe	approved copy of this form is to be sent) New Mexico 88210 When Plug Back Same Res'v. Diff. Res
Name of Authorized Transporter of Car Southern Union Ge If well produces oil or liquids, give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded 9-13-64	or Condense singhead Gas or or or \mathbf{K} . The following singhead \mathbf{K} or	Dry Gas Twp. Rge. 215 245 er lease or pool, 1 Gas Well X to Prod.	Address (Give address to which Address (Give address to which Box 199, Artesia, Is gas actually connected? No give commingling order number New Well Workover Deeper X Total Depth	n Club Bldg., Abilene, Temapproved copy of this form is to be sent) New Mexico 88210 When Plug Back Same Res'v. Diff. Res
Name of Authorized Transporter of Car Southern Union Ge If well produces oil or liquids, give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded 9-13-64 Fool	or Condense or Con	Dry Gas Twp. Rge. 215 245 er lease or pool, 1 Gas Well X to Prod.	Address (Give address to which and Address (Give address to which a Box 199, Artosia, Is gas actually connected? No give commingling order number New Well Workover Deeper X Total Depth Top Oil/Gas Pay	approved copy of this form is to be sent) New Mexico 88210 When Plug Back Same Res'v. Diff. Res
Name of Authorized Transporter of Car Southern Union Ga If well produces oil or liquids, give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded 9-13-64 Frool Indian Basin	or Condense or Con	Dry Gas Twp. Rge. 215 245 er lease or pool, 1 Gas Well X to Prod.	Address (Give address to which address (Give address to which address to which address to which address (Give address to which address (Give address to which address (Give address to which addr	approved copy of this form is to be sent) New Mexico 88210 When Plug Back Same Res'v. Diff. Res P.B.T.D. Tubing Depth
Name of Authorized Transporter of Car Southern Union Ga If well produces oil or liquids, give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded 9-13-64 Freel Indian Basin Perforations	or Condense or Con	Twp. Rge. 215 24E er lease or pool, Gas Well X to Prod.	Address (Give address to which and Address (Give address to which a Box 199, Artosia, Is gas actually connected? No give commingling order number New Well Workover Deeper X Total Depth Top Oil/Gas Pay	approved copy of this form is to be sent) New Mexico 88210 When Plug Back Same Res'v. Diff. Reserved P.B.T.D. P.B.T.D. Y423 Depth Casing Shoe
Name of Authorized Transporter of Car Southern Union Ga If well produces oil or liquids, give location of tanks. If this production is commingled wi COMPLETION DATA Designate Type of Completion Date Spudded 9-13-64 Feel Indian Basin	singhead Gas or singhead Gas or Soc. Unit Sec. 1 31 th that from any othe on - (X) Date Compl. Ready to 11-5-64 Name of Producing F Norrow	Twp. Rge. 215 24E er lease or pool, Gas Well X to Prod. Formation	Address (Give address to which address (Give address to which address to which address to which address (Give address to which address (Give address to which address (Give address to which address to which address (Give address to which address	approved copy of this form is to be sent) New Mexico 88210 When Plug Back Same Res'v. Diff. Res P.B.T.D. Tubing Depth 9423
Name of Authorized Transporter of Car Southern Union Ga If well produces oil or liquids, give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded 9-13-64 Freel Indian Basin Perforations	or Condense singhead Gas or	Dry Gas X Twp. Rge. 215 24E er lease or pool, Gas Well X Two Prod. Sormation 9601-04 IG, CASING, AN	Address (Give datess to which and Address (Give address to which a Box 199, Artesia, Is gas actually connected? No give commingling order number New Well Workover Deeper X Total Depth Top Oil/Gas Pay 9544	m Club Bldg., Abilene, Temaproved copy of this form is to be sent) New Mexico 88210 When Plug Back Same Res'v. Diff. Res P.B.T.D. P.B.T.D. YA23 Depth Casing Shoe 7728
Name of Authorized Transporter of Car Southern Union Ga If well produces oil or liquids, give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded 9-13-64 Fool Indian Basin Perforations	or Condense singhead Gas or as Co. Unit Sec. 7 I 31 th that from any other on - (X) Date Compl. Ready to 11-5-64 Name of Producing F Morrow 9584-86 TUBIN CASING & TU	Dry Gas X Twp. Rge. 215 24E er lease or pool, Gas Well X Formation 9601-04 IG, CASING, AN JBING SIZE	Address (Give datess to which and Address (Give address to which a Box 199, Artesia, Is gas actually connected? No give commingling order number New Well Workover Deeper X Total Depth Top Oil/Gas Pay 9544 D CEMENTING RECORD DEPTH SET	m Club Bldg., Abilene, Temaproved copy of this form is to be sent) New Mexico 88210 When Plug Back Same Res'v. Diff. Res P.B.T.D. P.B.T.D. PA23 Depth Casing Shoe 9728 SACKS CEMENT
Name of Authorized Transporter of Car Southern Union Go If well produces oil or liquids, give location of tanks. If this production is commingled wi COMPLETION DATA Designate Type of Completion Date Spudded 9-13-64 Fool Indian Basin Perforations 9544-46	or Condense singhead Gas or	Dry Gas X Twp. Rge. 215 24E er lease or pool, Gas Well X Two Prod. Sormation 9601-04 IG, CASING, AN	Address (Give datess to which a second process (Give address to which a second process to which	m Club Bldg., Abilene, Temapproved copy of this form is to be sent) New Mexico 88210 When Plug Back Same Res'v. Diff. Res P.B.T.D. P.B.T.D. PA23 Depth Casing Shoe 9728 SACKS CEMENT
Name of Authorized Transporter of Car Southern Union Go If well produces oil or liquids, give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded 9-13-64 Fool Indian Basin Perforations 9544-46 HOLE SIZE	or Condense singhead Gas or as Co. Unit Sec. I. 31 Ath that from any other on — (X) Date Compl. Ready to 11—5—64 Name of Producing F Norrow 9584—86 TUBIN CASING & TU	Dry Gas X Twp. Rge. 215 24E er lease or pool, Gas Well X Formation 9601-04 IG, CASING, AN JBING SIZE	Address (Give datess to which and Address (Give address to which a Box 199, Artesia, Is gas actually connected? No give commingling order number New Well Workover Deeper X Total Depth Top Oil/Gas Pay 9544 D CEMENTING RECORD DEPTH SET	Tubing Depth P.B.T.D. P.B.T.D. SACKS CEMENT TOO 965
Name of Authorized Transporter of Car Southern Union Go If well produces oil or liquids, give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded 9-13-64 Freel Indian Besin Perforations 9544-46 HOLE SIZE 18 12 1/4	or Condense or Con	Dry Gas X Twp. Rge. 215 215 er lease or pool, 1 Gas Well 2 X To Prod. Cormation 9601-04 IG, CASING, AN JBING SIZE	Address (Give datess to which a second process (Give address to which a second process to which	approved copy of this form is to be sent) New Mexico 88210 When Plug Back Same Res'v. Diff. Reserved Diff.
Name of Authorized Transporter of Car Southern Union Ga If well produces oil or liquids, give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded 9-13-64 Fool Indian Basin Perforations 9544-46 HOLE SIZE 18 12 1/4 8 3/4	or Condense singhead Gas or as Co. Unit Sec. F. 31 Ith that from any other on — (X) Date Compl. Ready to 11-5-64. Name of Producing F. Morrow 9584-86 TUBIN CASING & TU 13 3/8 9 5/3	Twp. Rge. 215 24E er lease or pool, Gas Well X To Prod. Corn.ation G, CASING, AN JBING SIZE 48 36 23 48 23 48 23 48 23 48 23 48 23 48 23 48 23 48 23 48 23 48 23 48 23 48 23 48 23 48 23 48 23 48 23 48 23 48 23 48 23 48 23 48 23 48 23 48 24 25 48 26 26 27 28 28 28 28 28 28 28 28 28	Address (Give datess to which and Address (Give address to which are Rox 199, Artosia, and Is gas actually connected? No give commingling order number New Well Workover Deeper X Total Depth Top Oil/Gas Pay 9544 D CEMENTING RECORD DEPTH SET 320 1785 8174	Tubing Depth P.B.T.D. P.B.T.D. SACKS CEMENT TOO SACKS CEMENT
Name of Authorized Transporter of Car Southern Union Go If well produces oil or liquids, give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded 9-13-64 Fool Indian Basin Perforations 9544-46 HOLE SIZE 18 12 1/4 8 3/4 6 1/8 TEST DATA AND REQUEST F	or Condense singhead Gas or as Co. Unit Sec. 7 Last the that from any other on - (X) Date Compl. Ready to 11-5-64 Name of Producing F Morrow 9584-86 TUBIN CASING & TUBIN CASING & TUBIN 13 3/8 9 5/8 7 4 1/2	Dry Gas X Twp. Rge. 21S 24E er lease or pool, Gas Well X To Prod. Cormation 9601-04 G, CASING, ANI JBING SIZE 48# 23# & 26# 11.6# links	Address (Give datess to which the Box 199, Artesia, Is gas actually connected? No give commingling order number to which the Box 199, Artesia, Is gas actually connected? No give commingling order number to be with the Box 199, Artesia, Is gas actually connected? No give commingling order number to be with the Box 199, Artesia, Is gas actually connected? No give commingling order number to be with the Box 199, Artesia, Is gas actually connected? No give commingling order number to be provided to be addressed to which the Box 199, Artesia, Is gas actually connected? No give commingling order number to be provided to be provi	n Club Bldg., Abilene, Tempapproved copy of this form is to be sent) New Mexico 88210 When Plug Back Same Res'v. Diff. Res P.B.T.D. P.B.T.D. PA23 Depth Casing Shoe 9728 SACKS CEMENT 700 965 400 175
Name of Authorized Transporter of Car Southern Union Ga If well produces oil or liquids, give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded 9-13-64 Fool Indian Basin Perforations 9544-46 HOLE SIZE 18 12 1/4 8 3/4 6 1/8	or Condense singhead Gas or as Co. Unit Sec. 7 Last the that from any other on - (X) Date Compl. Ready to 11-5-64 Name of Producing F Morrow 9584-86 TUBIN CASING & TUBIN CASING & TUBIN 13 3/8 9 5/8 7 4 1/2	Dry Gas X Twp. Rge. 21S 24E er lease or pool, Gas Well X To Prod. Cormation 9601-04 G, CASING, ANI JBING SIZE 48# 23# & 26# 11.6# links	Address (Give datess to which and Address (Give address to which are Rox 199, Artosia, and Is gas actually connected? No give commingling order number New Well Workover Deeper X Total Depth Top Oil/Gas Pay 9544 CEMENTING RECORD DEPTH SET 320 1785 8174 7728	A Club Bldg., Abilene, Tempapproved copy of this form is to be sent) New Mexico 88210 When Plug Back Same Res'v. Diff. Res P.B.T.D. P.B.T.D. SACKS CEMENT 700 965 400 175 and oil and must be equal to or exceed top all
Name of Authorized Transporter of Car Southern Union Ga If well produces oil or liquids, give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded 9-13-64 Fool Indian Basin Perforations 9544-46 HOLE SIZE 18 12 1/4 8 3/4 6 1/8 TEST DATA AND REQUEST FOIL WELL	or Condense singhead Gas or as Co. Unit Sec. 7 1 31 Ith that from any other on - (X) Date Compl. Ready to 11-5-64 Name of Producing F Morrow 9584-86 TUBIN CASING & TUB	Dry Gas X Twp. Rge. 21S 24E er lease or pool, Gas Well X To Prod. Cormation 9601-04 G, CASING, ANI JBING SIZE 48# 23# & 26# 11.6# links	Address (Give datess to which to Box 199, Artosia, Is gas actually connected? No give commingling order number New Well Workover Deeper X Total Depth Top Oil/Gas Pay 9544 DEPTH SET 320 1785 8174 9728 after recovery of total volume of locepth or be for full 24 hours)	A Club Bldg., Abilene, Tempapproved copy of this form is to be sent) New Mexico 88210 When Plug Back Same Res'v. Diff. Res P.B.T.D. P.B.T.D. SACKS CEMENT 700 965 400 175 and oil and must be equal to or exceed top all
Name of Authorized Transporter of Car Southern Union Ga If well produces oil or liquids, give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded 9-13-64 Fool Indian Basin Perforations 9544-46 HOLE SIZE 18 12 1/4 8 3/4 6 1/8 TEST DATA AND REQUEST FOIL WELL Date First New Oil Run To Tanks	or Condense singhead Gas or as Co. Unit Sec. F. 31 Ath that from any other on — (X) Date Compl. Ready to 11—5—64 Name of Producing F. Norrow 9584—86 TUBIN CASING & TU 13 3/8 9 5/8 7 4 1/2 FOR ALLOWABLE	Dry Gas X Twp. Rge. 21S 24E er lease or pool, Gas Well X To Prod. Cormation 9601-04 G, CASING, ANI JBING SIZE 48# 23# & 26# 11.6# links	Address (Give datess to which the Rox 199, Artosia, Is gas actually connected? No give commingling order number New Well Workover Deeper X Total Depth Top Oil/Gas Pay 9544 D CEMENTING RECORD DEPTH SET 320 1785 8174 9728 Inter recovery of total volume of lowerth or be for full 24 hours) Producing Method (Flow, pump,	Tubing Depth SACKS CEMENT TOO SACKS CEMENT TOO Sass lift, etc.)
Name of Authorized Transporter of Car Southern Union Ga If well produces oil or liquids, give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded 9-13-64 Fool Indian Basin Perforations 9544-46 HOLE SIZE 18 12 1/4 8 3/4 6 1/8 TEST DATA AND REQUEST FOIL WELL Date First New Oil Run To Tanks Length of Test	or Condense singhead Gas or as Co. Unit Sec. F. 31 Ith that from any other on — (X) Date Compl. Ready to 11–5–64. Name of Producing F. Morrow 9584–86 TUBIN CASING & TU 13 3/8 9 5/3 7 4 1/2 FOR ALLOWABLE Date of Test Tubing Pressure	Dry Gas X Twp. Rge. 21S 24E er lease or pool, Gas Well X To Prod. Cormation 9601-04 G, CASING, ANI JBING SIZE 48# 23# & 26# 11.6# links	Address (Give datess to which a second producing Method (Flow, pump, Casing Pressure	A Club Bldg., Abilene, Tempapproved copy of this form is to be sent) New Mexico 88210 When Plug Back Same Res'v. Diff. Reserved P.B.T.D. P.B.T.D. PASS 9824 Tubing Depth 9423 Depth Casing Shoe 9728 SACKS CEMENT 700 965 400 175 and oil and must be equal to or exceed top all gas lift, etc.) Choke Size
Name of Authorized Transporter of Car Southern Union Go If well produces oil or liquids, give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded 9-13-64 Fool Indian Basin Perforations 9544-46 HOLE SIZE 18 12 1/4 8 3/4 6 1/8 TEST DATA AND REQUEST FOIL WELL Date First New Oil Run To Tanks Length of Test Actual Prod. During Test	or Condense singhead Gas or as Co. Unit Sec. F. 31 Ith that from any other on — (X) Date Compl. Ready to 11–5–64. Name of Producing F. Morrow 9584–86 TUBIN CASING & TU 13 3/8 9 5/3 7 4 1/2 FOR ALLOWABLE Date of Test Tubing Pressure	Dry Gas X Twp. Rge. 21S 24E er lease or pool, Gas Well X To Prod. Cormation 9601-04 G, CASING, ANI JBING SIZE 48# 23# & 26# 11.6# links	Address (Give datess to which a second producing Method (Flow, pump, Casing Pressure	Tubing Depth SACKS CEMENT TOO SACKS CEMENT TOO Gas-MCF Approved copy of this form is to be sent) New Mexico 88210 When Plug Back Same Res'v. Diff. Res P.B.T.D. SACKS CEMENT TOO SACKS CEMENT TOO Gas-MCF
Name of Authorized Transporter of Car Southern Union Ga If well produces oil or liquids, give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded 9-13-64 Fool Indian Basin Perforations 9544-46 HOLE SIZE 18 12 1/4 8 3/4 6 1/8 TEST DATA AND REQUEST FOIL WELL Date First New Oil Run To Tanks Length of Test	or Condense singhead Gas or as Co. Unit Sec. F. 31 Ith that from any other on — (X) Date Compl. Ready to 11–5–64. Name of Producing F. Morrow 9584–86 TUBIN CASING & TU 13 3/8 9 5/3 7 4 1/2 FOR ALLOWABLE Date of Test Tubing Pressure	Dry Gas X Twp. Rge. 21S 24E er lease or pool, Gas Well X To Prod. Cormation 9601-04 G, CASING, ANI JBING SIZE 48# 23# & 26# 11.6# links	Address (Give datess to which a second producing Method (Flow, pump, Casing Pressure	The Club Bldg., Abilene, Temperoved copy of this form is to be sent) New Mexico 88210 When Plug Back Same Res'v. Diff. Reserved Plug Back Diff. Reserved P
Name of Authorized Transporter of Car Southern Union Ga If well produces oil or liquids, give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded 9-13-64 Fool Indian Basin Perforations 9544-46 HOLE SIZE 18 12 1/4 8 3/4 6 1/8 TEST DATA AND REQUEST FOIL WELL Date First New Oil Run To Tanks Length of Test Actual Prod. During Test GAS WELL Actual Frod. Test-MCF/D	or Condense singhead Gas or as Co. Unit Sec. F. 31 Ith that from any other on — (X) Date Compl. Ready to 11—5—64. Name of Producing F. Norrow 9584—86 TUBIN CASING & TU 13 3/8 9 5/8 7 4 1/2 FOR ALLOWABLE Date of Test Tubing Pressure Oil-Bbls.	Twp. Rge. 215 24E er lease or pool, Gas Well X To Prod. Cormation Soll-O4 G, CASING, AN JBING SIZE 48# 23# & 24# 11.6# links (Test must be able for this d	Address (Give address to which and the state of the state	The Club Bldg., Abilene, Texas approved copy of this form is to be sent) New Mexico 88210 When Plug Back Same Res'v. Diff. Resemble 19423 P.B.T.D. P.B.T.D. SACKS CEMENT 700 965 400 175 and oil and must be equal to or exceed top all gas lift, etc.) Choke Size Gas-MCF
Name of Authorized Transporter of Car Southern Union Ca If well produces oil or liquids, give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded 9-13-64 Fool Indian Basin Perforations 9544-46 HOLE SIZE 18 12 1/4 8 3/4 6 1/8 TEST DATA AND REQUEST FOIL WELL Date First New Oil Run To Tanks Length of Test Actual Prod. During Test GAS WELL Actual Prod. Test-MCF/D 4341	singhead Gas or as Co. Unit Sec. F. 31 Ith that from any other On - (X) Date Compl. Ready to 11-5-64 Name of Producing F. Norrow 9584-86 TUBIN CASING & TU 13 3/8 9 5/8 7 4 1/2 FOR ALLOWABLE Date of Test Tubing Pressure Oil-Bbls.	Twp. Rge. 215 24E er lease or pool, Gas Well X to Prod. Cormation 9601-04 IG, CASING, AN JBING SIZE 48# 23# & 24# 11.6# link (Test must be able for this decoration)	Address (Give address to which and the state of the state	The Club Bldg., Abilens, Texts approved copy of this form is to be sent) New Mexico 88210 When Plug Back Same Res'v. Diff. Resemble 19423 P.B.T.D. P.B.T.D. SACKS CEMENT 700 965 400 175 and oil and must be equal to or exceed top allows as lift, etc.) Choke Size Gas-MCF Gravity of Condensate
Name of Authorized Transporter of Car Southern Union Ga If well produces oil or liquids, give location of tanks. If this production is commingled with the completion of tanks. Designate Type of Completion Date Spudded 9-13-64 Fool Indian Basin Perforations 9544-46 HOLE SIZE 18 12 1/4 8 3/4 6 1/8 TEST DATA AND REQUEST FOIL WELL Date First New Oil Run To Tanks Length of Test Actual Prod. During Test GAS WELL Actual Prod. Test-MCF/D	singhead Gas or or or condense	Twp. Rge. 215 24E er lease or pool, Gas Well X to Prod. Cormation 9601-04 IG, CASING, AN JBING SIZE 48# 23# & 24# 11.6# link (Test must be able for this decoration)	Address (Give address to which and the state of the state	A Club Bldg., Abilene, Tempapproved copy of this form is to be sent) New Mexico 88210 When Plug Back Same Res'v. Diff. Resemble 1

I hereby certify that the rules and regulations of the Oil Conservation Commission have been complied with and that the information given above is true and complete to the best of my knowledge and belief.

(Date)

Original signed by T. A. Dugan

(Signature)

Consulting Engineer (Title)

June 17, 1965

AN ADD BAS HON TO THE TITLE _ This form is to be filed in compliance with RULE 1104.

If this is a request for allowable for a newly drilled or deepened well, this form must be accompanied by a tabulation of the deviation tests taken on the well in accordance with RULE 111.

All sections of this form must be filled out completely for allowable on new and recompleted wells.

Fill out Sections I, II, III, and VI only for changes of owner, well name or number, or transporter, or other such change of condition.

Separate Forms C-104 must be filed for each pool in multiply completed wells.