Form 3160-5 (June 1990)	DEPARTMEN BUREAU OF L	ED STATES I OF THE INTERIOR AND MANAGEMENT AND S. 1st Stree D REPORTS ON WELLS storig NM 88	5. Lease Designation and Serial No.
SUNDRY NOTICES AND REPORTS ON WELLS rtesia, NM 8821 Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.			6. If Indian, Allottee or Tribe Name N/A
	SUBMIT	7. If Unit or CA, Agreement Designation	
 Type of Well Oit X Gas Well Other Name of Operator V Chevron U.S.A. Inc. Address and Telephone No. P.0. Box 1150, Midland, TX 79702 Location of Well (Footage, Sec., T., R., M., or Survey Description) 			8. Well Name and No. BOGLE FLATS UNIT GAS COM #1 9. API Well No. 30-015-10383 10. Field and Pool, or exploratory Area
1953' FNL & 1650' FEL UNIT G SEC. 3, T22S, R23E			INDIAN BASIN; UPPER PENN (GAS 11. County or Parish, State EDDY, NM
12. CHECK A	PPROPRIATE BOX(s)	TO INDICATE NATURE OF NOTICE, REF	PORT, OR OTHER DATA
Describe Proposed or Comple give subsurface local POH W/PROD EQPT. DUMP 2 SX SD ON F TST CSG 1000 PSI	Intent Intent Int Report Intel Operations (Clearly state all p tions and measured and true vertice SET RBP @ 7150', TS RBP. SET CICR AS REC	TYPE OF Ad Abandomment Recompletion Plugging Back Casing Repair Altering Casing Other ertinent details, and give pertinent dates, including estimated date al depths for all markers and zones pertinent to this work.)* ST TO 1000#. ISOLATE BAD CSG; ESTABLI QUIRED; CMT SQZ CSG, CIRC CMT TO SURF. & POH. RIH W/TBG & RODS. RETURN WELL	Change of Plans Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) of starting any proposed work. If well is directionally drills SH DID 9. DDESCUDE
 I hereby certify that the for Signed	regoing is true and correct		<u>Date 10/14/99</u> EER OCT 1 8 1999

* See Instruction on Reverse Side