

SF/Jul

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☐ other ☒ P&A

2. NAME OF OPERATOR ARCO Oil and Gas Company  
Division of Atlantic Richfield Company C. D.

3. ADDRESS OF OPERATOR  
P. O. Box 1710, Hobbs, New Mexico 88240


4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 960' FNL & 800' FWL  
AT TOP PROD. INTERVAL: as above  
AT TOTAL DEPTH: as above

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF <input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE <input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES <input type="checkbox"/>	<input type="checkbox"/>
ABANDON* <input type="checkbox"/>	<input checked="" type="checkbox"/>
(other)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

RU 4/1/82. Installed BOP. Set cmt retr @ 7478'. Cmt squeezed perfs 7552-58' w/ 100 sx Cl C cmt. RO 60 sx cmt. Left 10 sx on top of retr. Top of cmt plug @ 7360'. Circ 10# salt gel mud. Cut 4 1/2" csg @ 6166' and pulled. Spot 50 sx Cl C cmt plug 6266-6066' across 4 1/2" csg stub. Tagged cmt plug @ 6016' w/2-3/8" tbg. Spot 30 sx cmt plug 5000-4900'. RIH w/8-5/8" cmt retr, set @ 3500'. Squeeze cmt 8-5/8" csg shoe @ 3612' w/50 sx Cl C cmt, spot 50' cmt on top of retr. Spot 50 sx cmt plug 400'-200'. Cut off wellhead below GL. Set 10 sx cmt @ surf. Installed regulation dry hole marker. P&A eff 4/14/82. Cleaned and levelled location for abandonment. Final Report.



Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Dist Drlg Supt, DATE 4/26/82

APPROVED \_\_\_\_\_ (This space for Federal or State office use)

(Orig. Sgd.) PETER W. CHESTER  
APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

MAY 13 1982  
FOR  
JAMES A. GILLHAM  
DISTRICT SUPERVISOR

\*See Instructions on Reverse Side

5. LEASE  
NM-04787-B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME  
Walt Canyon Unit

8. FARM OR LEASE NAME  
Walt Canyon Unit

9. WELL NO.  
2

10. FIELD OR WILDCAT NAME  
Indian Basin Upper Penn Gas

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
4-22S-24E

12. COUNTY OR PARISH: 13. STATE  
Eddy New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB. AND WD)  
3965' DF

(NOTE: Report results of multiple completion or zone change on Form 9-330.)