

457

NEW MEXICO OIL & GAS COMMISSION
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
ARTESIA, NM 88001

SUMMARY NOTICES AND REPORTS ON WELLS

(This form is to be filled out by the operator of a well, or by a person authorized by the operator, and submitted to the Bureau of Land Management, Artesia, NM 88001, for filing and distribution to the appropriate agencies.)

1. Oil well ☒ Gas well ☒ Other ☐
2. NAME OF OPERATOR
Robert N. Enfield
3. ADDRESS OF OPERATOR
P.O. Box 2431, Santa Fe, NM 87501

RECEIVED BY
SEP - 5 1986
O. C. D.
ARTESIA, OFFICE

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
1650' FS & EL, Sec. 18
AT SURFACE:
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

5. WELL NO. 10 065300
6. FIELD OR WILDCAT NAME
7. UNIT/ZONE NAME
8. FARM OR RANCH NAME
9. WELL NO.
10. FIELD OR WILDCAT NAME
Indian Basin Upper Penn
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 18, T21S, R23E
12. COUNTY OR PARISH
Eddy
13. STATE
NM
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
4418' GL

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	☐		☐
FRACTURE TREAT	☐		☐
SHOOT OR ACIDIZE	☐		☐
REPAIR WELL	☐		☐
PULL OR ALTER CASING	☐		☐
MULTIPLE COMPLETE	☐		☐
CHANGE ZONES	☐		☐
ABANDON*	☐		☒

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Set CIBP at 6182' w/48' (4 sks) cement on top. Circ. hole w/9.5#/gal. salt water mud.
2. Casing free point (4-1/2") cut off at 5400'.
3. GIH w/tubing to approx. 5480' KB (75' into 4-1/2" stub). Pump 75 sx plug. Pump plug down w/9.5#/gal. salt water mud.
4. WOC, tagged cement plug w/tubing at 5290' (cement from 5480-5290')
5. Pump 65 sx plug at 5280' KB. Top of Wolfcamp formation
6. Pump 50 sx plug at 2830' KB. Top of Bone Springs formation.
7. Pump 60 sx plug at 1855' KB. Top of Gloriette formation.
8. Pump 75 sx plug at 1582' KB. 8-5/8"(sq. set @ 1532' KB) tagged cement at 1408' cement from 1582' - 1408'.
9. Pump 35 sx plug at 222' KB.
10. Pump 15 sx plug from 0'-50' KB.
11. Cut-off & installed dry hole marker, cleared & leveled location as required

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNATURE Robert N. Enfield OPERATOR
TITLE

DATE 9/85

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

Post ID-2
3-1-85
OKA