

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT-" for such proposals

SUBMIT IN TRIPLICATE

RECEIVED

1. Type of well
☐ Oil ☒ Gas ☐ Other

AUG 17 1992

2. Name of Operator
CHEVRON U.S.A. INC.

C. C. D.

3. Address and Telephone No. (915) 687-7812

P.O. BOX 1150 MIDLAND, TEXAS 79702 ATTN: P.R. MATTHEWS, ROOM 3104

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

SEC. 8, T22S, R23E
1650' FNL & 1650' FEL
UNIT G

5. Lease Designation and Serial No.

NM 045272

6. If Indian, Allottee or Tribe Name

N/A

7. If Unit or CA, Agreement Designation

N/A

8. Well Name and No.

BOGLE FLATS # 6

9. API Well No.

30-015-10578

10. Field and Pool, or Exploratory Area

INDIAN BASIN

11. County or Parish, State

EDDY CO, NEW MEXICO

CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

12	TYPE OF SUBMISSION	TYPE OF ACTION	
	<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
		<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut-Off
		<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection
		<input checked="" type="checkbox"/> Other PERF & STIMULATE	<input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimate date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

MIRU, POOH WITH PROD. EQUIP. TIH AND SET RBP AT 3719'.
TIH WITH CICR SET AT 2644', PUMP 600 SXS. CMT. INTO CICR.
DRILL OUT CICR AND CEMENT TO 3230. TEST CASING TO 500# FOR 15 MIN. OK.
TOH WITH RBP. LOG HOLE WITH PULSE-NEUTRON TDT.
PERFORATE WITH 4" GUNS, 90 DEG. PHSD, 4 JHPF, 7276-7308, 128 HOLES.
ACIDIZE PERFS WITH 5000 GALS OF 15% NEFE, FLOW WELL BACK.
TIH AND SET CICR AT 7240, PUMP 175 SXS. CMT INTO CICR. PBTB AT 7240'.
ACIDIZE PERFS 7064-7225 WITH 2000 GALS. OF 15% NEFE. FLOW WELL BACK.
PACKER SET AT 6988'.
RETURN WELL TO PRODUCTION.

AK

14. I hereby certify that the foregoing is true and correct

Signed P. R. Matthews

Title

TECHNICAL ASSISTANT

Date

8-28-92

(This space for Federal or State office use)

Approved by

Title

Date

Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and wilfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instructions on Reverse Side