

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN T
(Other instruct
reverse side)

ICATE*
of re

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐	7. UNIT AGREEMENT NAME Bogle Flats Unit
2. NAME OF OPERATOR Standard Oil Company of Texas	8. FARM OR LEASE NAME Bogle Flats Unit
3. ADDRESS OF OPERATOR A division of Chevron Oil Company 3610 Avenue S Snyder, Texas	9. WELL NO. 7
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit J, 1650' FSL & 1650' FRL of Section 7, T-22N, R-23E.	10. COUNTY OR PARISH Indean Basin, Upper Penn. Gas
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 7, T-22N, R-23E
15. ELEVATIONS (Show whether DF, RT, GR, etc.) Gr. 4197.3	12. COUNTY OR PARISH Indean
	13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☒	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) Supplementary Well History	4

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Supplementary Well History

Drilled ahead in 3 3/4" hole to 7436', ran DST No. 1 7428'-7530', recovered 240 ft. mud, 1320 ft. sulphur water, 2 ft. mud and cuttings. Drilled ahead in 3 1/4" hole to total depth of 8057 feet and logged. Ran DST No. 2 7917-8057, tool open 1-hour, weak blow immediately, died in 14 minutes, recovered 290 feet slight saltwater cut mud with sulphur odor.

Received verbal approval to P & A from USGS on November 11, 1963.

P & A Procedure

1. Run DP open ended. Set cement plugs as follows per USGS requirements: 7850'-8057', 7400'-7530', 6000'-6100', 4400-4500, 3250-3350, 1900-2050, 400-500'.
2. Release rig & move out.
3. Remove well HD eqpt. Set 10 sack cement plug in top of 9 5/8" casing.
4. Weld steel plate w/needle valve on 13 3/8" casing. Clean up and level location. Install abandoned well marker.

RECEIVED

NOV 11 1963

18. I hereby certify that the foregoing is true and correct

SIGNED **E. W. McCants** TITLE **District Engineer** DATE **11-12-63**

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.