

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPlicate
(Other Instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

45F

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

NAME OF OPERATOR

Yates Drilling Company

ADDRESS OF OPERATOR

105 South 4th Street, Artesia, New Mexico 88213

1. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

Unit N, 990' FSL & 1650' FWL

RECEIVED BY

MAR 25 1987

O. C. D.

ARTESIA, OFFICE

5. LEASE DESIGNATION AND SERIAL NO.

NM-05110-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Galvin Federal

9. WELL NO.

#7

10. FIELD AND POOL, OR WILDCAT

West McMillan SR - 4

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Section 12-20S-26E

12. COUNTY OR PARISH 13. STATE

Eddy

N.M.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREATMENT

REPAIR OR COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANT

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

X


(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

14. BRIEF PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Associated with the Brantley Dam Project, plugging responsibility and liability was assumed by the Bureau of Reclamation. Plugging was as follows:

- 1-22-87 Pulled tubing
Tagged bottom w/ 1" pipe at 82'
Circulated hole w/ water
Circulated hole w/ Class "C" cement
- 1-23-87 Cement fell
Topped cement off, held okay.

A surface marker will be erected and/or surface work completed as needed by Bureau of Reclamation.



15. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Engineer

DATE 2-25-87

This is a true and correct copy of the original State of New Mexico

Acting Area Manager

APPROVED BY

TITLE

DATE

3257

CONDITIONS OF APPROVAL, IF ANY.

Post ID-2
3-6-87
P4A

*See Instructions on Reverse Side