Form 3160-5 (August 1999)

UN D STATES DEPARTME... OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED	
OMB NO. 1004-0135	,
unicas Navambar 20. 2	٥

5. Lease Serial No.

MI	070522	Α

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUNDRY NOTICES AND REPORTS ON WELLS

6. If Indian, Allottee or Tribe Name

		2324	20		
SUBMIT IN TRIPLICATE - (Other instructions on	reverse side	25.26.2.1.30	7. If Unit or CA/Agreement, N	lame and/or No
Oil Well X Gas Well Other Name of Operator		SE S	7.93031 200	8. Well Name and No. INDIAN BASIN E #1	
Marathon Oil Company		<u> </u>	16.12	9. API Well No.	
a. Address	3b.	Phone No. (include area	(Cbde) A,	30-015-10617	
P.O. Box 552, Midland, TX 79702		915-682-1626	395	10. Field and Pool, or Explora INDIAN BASIN UPPER P	
Location of Well (Footage, Sec., T., R., M., or Survey L.	Description)	-0:68	<u>.</u> -	POOL	LINIT UAS
UL "K", 1650' FSL AND 1650' FWL				11. County or Parish, State	
SECTION 27, T-21-S, R-23-E				1	NM
			OTIOE DED	,	1111
12. CHECK APPROPRIATE	BOX(ES) TO INDICA	TE NATURE OF NO	JIICE, REP	URI, UR OTHER DATA	
TYPE OF SUBMISSION		TYPE	OF ACTION		
Notice of Intent	X Acidize	Deepen	=	(Start/Resume) Water Shu	
X Subsequent Report	Alter Casing	X Fracture Treat	Reclamation		•
A Subsequent Report	Casing Repair	New Construction	Recomple	te X Other S	<u>stimulate</u>
Final Abandonment Notice	Change Plans	Plug and Abandon	Temporari	ly Abandon <u>Horizonta</u>	<u>l Lateral</u>
Tima 7 bandstans 1 to 100	Convert to Injection	Plug Back	Water Dis	posal	
Work commenced on 5/9/00. MIRU P set & test. POOH & L/D RTTS pack pipe into lateral & hit bridge @ 10.331'. POOH & RIH w/bull plug Installed stripper head and start for a total of 24,000 gals. acid. pipe. L/D check valve & surgeifra L/D logging tool. RIH w/bent jt 10 runs recovering 55 bbls fluid. to 7761'. Unloaded bailer, NU se landed tbg in wellhead. ND BOP &	er. RIH w/AOH pip 8495'. PU swivel & on bottom and surg ed acid frac using Pumped 4000 gals ac tool. RIH w/GR m on tbg to 7765'. Made 28 runs receaboard head, & RIH	e, tagged vertical work pipe past less tool on AOH dried 20% CSA acid, the 20% CCA sour accessory tool to 10 PU & found windowering 135 bbls w/sub pump on pipers tool to pursub pump on pipers were provers tool to pursub pump on pipers tool to pump on pipers tool tool tool tool tool tool tool too	al hole @ . bridge. L. ill pipe to hen flush, cid down an ,270'. Lon w & RIH to fluid. Po roduction	7659', & PUH to Windo /D swivel & RIH to The bo bottom of lateral. followed by water w/ nnulus w/N2. POOH w/ gged lateral & POOH w 7934'. RU to swab. OOH L/D tbg. RIH w/b	w. Ran D @ biocide AOH /pipe Made ailer plice & 23/00.
				16	
14. I hereby certify that the foregoing is true and correct Name (Printed Typed) Ginny Larke		Title Enginee	r Tochnici	an	<u> </u>
	, , , , , , , , , , , , , , , , , , , ,	Date 6/2/00			
THI	S SPACE FOR FEDER	AL OR STATE OFF	ICE USE		
Approved by		Title		Date	
Conditions of approval, if any, are attached. Approval	of this notice does not warr	ant or Office			
conditions of approval, it any, are attached. Approval, certify that the applicant holds legal or equitable title to which would entitle the applicant to conduct operations	o those rights in the subject	lease			