

Texaco Inc. Box 728 Hobbs, New Mexico

Re: State DF Gas Com No. 1 K and No. 1Y K, 32-21-23, Indian Basin-Upper Pennsylvanian

1. 1.

Gentlemen:

A field inspection of the subject well sites reveals the following:

Well No. 1, the producing well, has no well sign as required. A considerable amount of junk is still scattered around the location and the pit for the No. 1Y well has not been filled and levelled.

Please attend to these matters at your earliest convenience and contact this office when the work has been done.

Very truly yours,

OIL CONSERVATION COMMISSION

R. L. Stamets Geologist