

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	3

RECEIVED

NEW MEXICO OIL CONSERVATION COMMISSION  
JUN 15 1966

O. C. C.  
ARTESIA, OFFICE

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. State - OG - 5108
7. Unit Agreement Name - - -
8. Farm or Lease Name State "DF" Gas Com.
9. Well No. 1-Y
10. Field and Pool, or Wildcat Indian Basin Upper Penn
12. County Eddy

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- DRY
2. Name of Operator TEXACO Inc.
3. Address of Operator P. O. Box 728 - Hobbs, New Mexico
4. Location of Well UNIT LETTER K, 1461 FEET FROM THE South LINE AND 2542 FEET FROM THE West LINE, SECTION 32 TOWNSHIP 21-S RANGE 23-E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) Unknown

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Subject well plugged and abandoned as listed below:

Total Depth - 425'  
13 3/8" O. D. Casing Cemented at 196'

1. Cement with 150 Sx. cement plus 5 Sx. Floseal.
2. Cement at 200', fill up 13 3/8" O. D. Casing with 200 Sx. cement plus 5 Sx. Floseal, with cement circulated to surface.
3. Install 4" marker extending 4' above ground level, clean the location for inspection by the New Mexico Oil Conservation Commission Office, Artesia, New Mexico. Plug and abandon of well complete 7:00 P. M. June 10, 1966.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Dan Gillett</u>	TITLE <u>Assistant District Superintendent</u>	DATE <u>June 14, 1966</u>
APPROVED BY <u>R. L. Stam</u>	TITLE <u>OIL AND GAS</u>	DATE <u>MAR 21 1967</u>
CONDITIONS OF APPROVAL, IF ANY:		