		N. M. U. U.	-	Copy Z
Form 9-331 (May 1963)	DEPART	TED STATES T OF THE INTERIO	(Other Instru	ICATE• on re- 5. LEASE DESIGNATION AND SERIAL P
*******	GEOLO	OGICAL SURVEY		NM 030482
		AND REPORTS ON drill or to decpen or plug bac FOR PERMIT-" for such prop	k to a different reservoir	6. IF INDIAN, ALLOTTEE OR TRIBE NA
1.			RECEN	7. UNIT AGREEMENT NAME
OIL GAS WELL WELL	X OTHER		ECEN	Indian Hills Unit
2. NAME OF OPERATOR	Manathan Oil C		RECNOV19	970 8. FARM OR LEASE NAME
3. ADDRESS OF OPERAT	Marathon UIL Co	ompany	NOVIS	9 9 MELL NO.
P.O. Box	2409, Hobbs, 1	New Mexico 882	40 - 5201001	
 2. NAME OF OPERATOR Marathon Oil Company Mov191970 MOV191970				10. FIELD AND POOL, OR WILDCAT
At surface	,		Str.	Indian Basin Upper Pe
1650' FSL & 1650' FWL of Sec. 28				11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
_			*	Sec. 28-215-24E
14. PERMIT NO. 15. ELEVATIONS (Show whether DF. RT. GR. etc.)				12. COUNTY OR PARIEN 13. STATE
		3782' GR		Eddy New Mex
10			· · · · · · · · · · · · · · · · · · ·	
16.		iate Box To Indicate Nat	ture of Notice, Repo	rt, or Other Data
	NOTICE OF INTENTION TO	D:		SUBSEQUENT REPORT OF:
TEST WATER SHUT	OFF PULL OF	R ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT		LE COMPLETE	FRACTURE TREATMEN	
SHOOT OR ACIDIZE	ABANDO CHANGE		SHOOTING OR ACIDIZ	
(Other)	CHA.02		(Norr: Report	results of multiple completion on Well Recompletion Report and Log form.)
(25') with 150	sacks Class "(C" cement with l_2^1 %	D 19 per sack	en hole from 7479 to 7504' . Final pump pressure d found no cement below
retainer. Tag	ged bottom @ 7	504' and no cement	in open hole.	
				"C" cement; first 100
				sack. Established rate
	3-1/2 B.P.M. @ 2400 psi. Maximum pressure 4000 psi. Reversed ou Drilled retainer and good cement from 7466-7483'.			
	8		- •	
Perforated 5-1/2" casing and open hole from 7478-79-80-81,				81, and 7482', 2 JSPF,
5' (10 holes).	· · · · · · · · · · · · · · · · · · ·			
On the st	a 11			
in due to diff	iculty experien	// MUIPU and 30 BS	ace equipment	nt time the well is shut and insufficient gas to
keep controls	operative. Los	ss of pressure on	separator cause	es water to be discharged
down gas flow	line.		r uttor tudo	
18. I hereby certify the	t the foregoing is true a	and correct.		
signed UU	tis K. An		ing Area Supt.	DATE <u>11-17-70</u>
(This space for Fee APPROVED BY CONDITIONS OF ED FOR RECORD	leral or State office use)		F	REPL
APPROVED BY CONDITIONS OF a	PRICOSE, IF MY :	TITLE		NOV 201070
TOR BECORD	1 K.h.			Nova
ED FUN	District Engineer	, 		
9 1970 ACTING	District me	*See Instructions o	n Reverse Side	D .
ACT I			2	U. C. C. RTESIA, OFFICE
ate R				" UFFICE