

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIP
(Other instructions
verse side)TE
FForm approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 014382

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Dry Hole	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Union Oil Company of California ✓	8. FARM OR LEASE NAME North Huapache Unit #23
3. ADDRESS OF OPERATOR P. O. Box 671 - Midland, Texas 79701	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 2,310' FNL and 1,980' FEL	10. FIELD AND POOL, OR WILDCAT Wildcat
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 23, T22S, R22E
14. PERMIT NO.	12. COUNTY OR PARISH Eddy
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4,351' GL	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☒CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Verbal approval to abandon received from Mr. Jim Knauf to J. L. White April 12, 1966. Plan to set 50 sacks cement plug 7,510'-7,370', 50 sack cement plug 6,000'-5,850', 50 sack plug 3,850'-3,700', 50 sack cement plug 1,980'-1,830'. 10 sack cement plug 30' to GL. Weld plate on top of 8-5/8" casing and set dry hole marker. Location to be cleaned and leveled after pits are dry.

RECEIVED

JUN 23 1966

O. C. C.
ARTESIA, OFFICERECEIVED
JUN 20 1966
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE District Office Manager

DATE June 16, 1966

(This space for Federal or State office use)

APPROVED BY
CONDITION OF APPROVAL, IF ANYAPPROVED
JUN 21 1966
RUDOLPH C. BAIER, JR.
ACTING DISTRICT ENGINEER

TITLE

DATE

*See Instructions on Reverse Side